



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS3/SMO23000647/Kwy3m4

Date: 01/03/2023

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 4304S	Veh. Inspected	SKN 3313Z
Policy No.	D22MTPCVE002565	Coverage (\$)	0.00
Claim No.	CMTD2204392/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	19/01/2023

2. Vehicle Particulars & Condition


Make & Model	BMW 523I (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAFP32040C544985	Colour	METALLIC DARK GREY
Odometer	209913 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	MICHELIN	5 mm
L/H Front Tyre	225/55 R17	MICHELIN	5 mm
R/H Rear Tyre	225/55 R17	MICHELIN	5 mm
L/H Rear Tyre	225/55 R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.



5. General Information

Accident Date	06/10/2022	Inspect Date / Time	17/02/2023 (01:36 PM)
Survey held at	ASTUTE AUTOWORKS PTE LTD 60 JALAN LAM HUAT, #02-16/17, CARROS CENTRE SINGAPORE 737869		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**

Report Ref No. CS3/SMO23000647/Kwy3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.