

Section A - Accident Details

Registration Number	SHB261H
Case Reference Number	TAX/01/23/2043
Registration Date	29/Dec/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	MOHAMMAD HERMI BIN BUANG
Type of Accident	Side Swipe
Accident Date and Time	19/Jan/2023 7:40 AM
Accident Reported Date and Time	19/Jan/2023 8:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24117474
Special Instruction to ARC, if any	TP
Prepared Date and Time	19/Jan/2023 9:43 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,200.00	\$600.00
Total Spray Cost	\$856.00	\$440.00
Total Spare Part Cost	\$5,176.19	\$2,589.07
Total Other Cost	\$880.00	\$380.00
TOTAL COST	\$8,112.19	\$4,009.07 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / China Taiping
ARC / Surveyor Sign Off Date	20/01/2023 1:52 PM	20/01/2023 12:25 PM
Signature		
Remarks	PART BY PART / Before paint photo ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL:	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2302-0146	Invoice Number	
Quotation Date	15.02.2023	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$1,200.00	\$600.00 ✓
Total Labour	\$1,200.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$428.00	\$220.00 ✓
TO RESPRAY FRONT FENDER LH	\$428.00	\$220.00 ✓
Total Spray Painting & Panel Beating	\$856.00	\$440.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$50.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00 ✓
ISOLATED OF (EV) (NET)	\$150.00	\$150.00 ✓
Total Other Costs	\$880.00	\$380.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		50004880-SEPP	BRACKET-F/FDR FRT LWR - LH	0.00	\$15.81	0.00	\$0.00	Replace	Check
		10872987	BRACKET-F/CMPT TR PLT	0.00	\$55.33	0.00	\$0.00	Replace	Not Given
		10737506	BRACKET-F/CMPT TR PLT	0.00	\$44.51	0.00	\$0.00	Replace	Check
		10361097	FINISHER-FRT FOG LP CVR - LH	1.00	\$47.32	10.00	\$42.59	Replace	Replace
		10361099	COVER-FRT FOG LP - LH	1.00	\$40.25	10.00	\$36.23	Replace	Replace
		10825313	DEFLECTOR-U/B FRT	0.00	\$169.72	0.00	\$0.00	Replace	Check
		10892857	LINER ASM-FRT W/H - LH	0.00	\$125.22	0.00	\$0.00	Replace	Check
		10361101	GRILLE-FRT BPR FASCIA LOWER	1.00	\$149.03	10.00	\$134.13	Replace	Replace
		10446164	FINISHER-FRT BPR LOWER - LH	1.00	\$20.38	10.00	\$18.34	Replace	Replace
		10361095	FINISHER-FRT BPR - LH	1.00	\$98.80	10.00	\$88.92	Replace	Replace
		10751682	SUPPORT-FRT BPR FASCIA UPR	0.00	\$172.33	0.00	\$0.00	Replace	Check
		10751567	HEADLAMP ASM -LH	1.00	\$1,098.86	10.00	\$988.97	Replace	Replace
		10236735-SEPP	FENDER ASM-FRT - L	1.00	\$379.81	10.00	\$341.83	Replace	Replace

X
X X NN
X
✓ DIS
✓ DE
X
X
✓ DE
✓ DE
✓ CRA
X
✓ CRA
✓ BT

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/02/2023

User ID : PohSuan

		10879244	MODULE-FRT END	0.00	\$295.26	0.00	\$0.00	Replace	Check	X
		10894738	BRACKET ASM-HDLP UPP - LH	0.00	\$22.57	0.00	\$0.00	Replace	Check	X XNN
		10954633	PANEL ASM-LEG CTHR	0.00	\$131.04	0.00	\$0.00	Replace	Check	X
		10892798-SEPP	BAR ASM-FRT BPR IMP	0.00	\$624.00	0.00	\$0.00	Replace	Check	X
		10325882-SPRP	FASCIA-FRT BPR	1.00	\$721.66	10.00	\$649.49	Replace	Replace	√ DE
		10326366	BRACKET-FRT BPR FASCIA - LH	0.00	\$23.09	0.00	\$0.00	Replace	Check	X
		10751478	GRILLE ASM-RAD	0.00	\$978.02	0.00	\$0.00	Replace	Check	X XNN
		10737505	COVER-F/CMPT ORNA	0.00	\$217.67	0.00	\$0.00	Replace	Not Given	X
Total					\$5,430.68		\$2,300.50			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		10825313	DEFLECTOR-U/B FRT	1.00	\$169.72	10.00	\$152.75	Replace	Replace de
		10326366	BRACKET-FRT BPR FASCIA - LH	1.00	\$23.09	10.00	\$20.78	Replace	Replace de
		10892857	LINER ASM-FRT W/H - LH	1.00	\$125.22	10.00	\$112.70	Replace	Replace de
		91000089	CLIP-FRT BPR FASCIA BRKT	1.00	\$2.60	10.00	\$2.34	Replace	Replace de
Total					320.63		288.57		

2,589.07
+ 600.00
+ 820.00
4,009.07