



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Tel: 9101 7844

Business Reg. No.: 53387981K

Fax: 6996 6442

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/2206/FY129K/SM

ASSESSMENT FOR REPAIR : FY129K

Qty	Description	Condition	Repairer's Estimate	Our Assessment
1 pc	Handle bar	Distorted	84.00	84.00 ✓
1 pc	Brake lever X	Usable	25.00	~
1 pair	Mirror	Bent / Cut	80.00	80.00 ✓
1 pc	Handle bar rear cover	Broken	69.00	69.00 ✓
1 pc	Headlight cover	Broken	74.00	74.00 ✓
1 pair	Front signal light	Cut	84.00	84.00 ✓
1 pc	Headlight unit	Cracked	90.00	90.00 ✓
2 pcs	Fork Assy @280.00 225 @	Bent	560.00	560.00 450
1 pc	Fork under bracket	Bent	155.00	155.00 ✓
1 pc	Front fender	Broken	75.00	75.00 65
1 pc	Front wheel XSVL	Cut / Warped	370.00	370.00 X
1 pc	Front wheel axle	Bent	32.00	32.00 8 5/2
1 pc	Front brake disc XSVL	Cut	116.00	116.00 X
1 pc	Front stay	Distorted	48.00	48.00 ✓
2 pcs	Leg shield complete @96.00 42	Cut	192.00	192.00 84
2 pcs	Leg shield inner cover @86.00 65	Broken / Cracked	172.00	172.00 130
1 pc	Front footrest bar	Cut / Bent 36	64.00	64.00 ✓
1 set	Front footrest rubber	Cut	25.00	25.00 18
2 pcs	Rear cover @112.00	Perforated / Cracked	224.00	224.00 ✓
1 pc	Muffler protector X	Cut	82.00	82.00 X
		Less 10%	2,621.00	2,596.00 1719
			262.10	259.60 102
			2,358.90	2,336.40 1547.10

Special Nett Items

1 pc	Front number plate	Necessary	20.00	18.00 10
1 set	Steering cone & bearing	Necessary	100.00	60.00 40
1 pc	Front basket & bracket	Bent	50.00	45.00 30
1 pc	Rear top box X	Missing	125.00	125.00 X
1 pc	Rear rack X	Bent	120.00	100.00 X
			415.00	348.00

Total Parts

2,773.90 2,684.40

Labour Charges

1	Towing fee	80.00	60.00 X
2	Transfer tyre, balance wheel & align steering components	200.00	180.00 100
3	Spray painting for body covers	450.00	400.00 300
4	Renew damaged parts & repair affected areas	500.00	450.00 350
		1,230.00	1,090.00

Total Parts & Labours Concluded

4,003.90

Lump Sum Repair Adjustment

3,000.00



LEE APPRAISAL SERVICES

220A Sumang Lane #06-75 (S)821220

Tel: 9101 7844

Fax: 6996 6442

Business Reg. No.: 53387981K

Email: dylanlee.as@gmail.com

Loss Adjuster, Automotive Inspection, Evaluation & Consultation

Our Reference : TP/2206/FY129K/SM

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment above.

1547.10
8.00
80.00
750.00
2385.10
202
1908.08
115-\$1,900 / 4 days

Yours faithfully,
LEE APPRAISAL SERVICES

Lee Kah Pang
Dip. Mech Engr, BCompSc

