## \* PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** 

: ACCIDENT REPAIRS

WORKSHOP

: UBI ROAD 1

CONTACT NO FAX NO

: 6366 2323 : 6841 1183

REFERENCE

: PA/OD/0047/2023/EQ

DATE

14-Jan-23

WIP

59139

# VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/1/2023

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME

MR LIM KOK TIONG

ADDRESS

BLK 30 AMBER GARDENS

#04-01

SINGAPORE 439964

**TELEPHONE** 

HP +65 97468897

TYPE OF CLAIM

OWN DAMAGE CLAIM

POLICY NO

7220151500

**VEHICLE NO** 

SN] 1770 K

MODEL CODE

AUDI A7 SPORTBACK 2.0 TFS

MODEL YEAR

28/12/2022

ENGINE NO

DKY 016451

**CHASSIS NO** 

WAUZZZF25NN008645

MILEAGE

DATE IN

ESTIMATED BY

: JOHNNY BOO / ALLAN WU

ACCIDENT DATE

10-Jan-23

PLACE OF ACCIDENT

: KM 13 JLN JOHOR BAHRU - AIR HITAM TOWARDS DANGA BAY,

MALAYSIA





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNJ 1770 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N	\$ 360.00	/ /
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$	500
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.		\$ 2,000.00	5 SO ·
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	/ /
	TOTAL LABOUR CHARGES	:	\$ 4,152.00	=





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNJ 1770 K

			DAMAGED PARTS & PRICES		
	PARTS DESCRIPTION	QTY		S/NETT REMARKS	
S/N	PARIS DESCRIPTION			2011	
1	REAR BUMPER Delec	1	\$	3,677.00 - 2941.60	
		1	\$	259.00	
2	REAR BUMPER FIXING PARTS  REAR BUMPER SECURING STRIP - LH / RH  We W	2	\$	102.00	
3	REAR BUMPER SPOILER L	1	\$	565.00 HEI-60	
4	REAR BUMPER CHROME TRIM - CENTER at	1	\$	261.00 - >08.80	
5	REAR BUMPER CHROME TRIM - LH / RH XH LL	2	\$	530.00 🗡	
6		1	\$	688.00 7 550 10	
7	REAR BUMPER CHROME THE	1	5	204.00 7	
8	REAR BUMPER SECURING STRIP  REAR PROOF LID OPENING CONTROL UNIT	1	\$	491.00 +	
9	REAR BOOT LID OF ENTING CONTINGED	_	\$	460.00 /	
10	REAR TAILGATE OPENING SENSOR LINE - LH / RH	_	\$	123.00	
11	REAR AERIAL KEY ACCESS	1		897.00 F	
12	REAR PARKING AID SENSOR - INNER / OUTER	3	\$		
13	REAR PARKING AID SEAL RING	4	\$	11.00 \$	
14	REAR BUMPER WIRING SET	1	\$	648.00	
15	210		\$	400.00	
	TOTAL SPARE PARTS	:	\$	9,316.00	
	TOTAL LABOUR CHARGES	:	\$	4,152.00	
	GRAND TOTAL	:	\$	13,468.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

#### **PREMIUM** AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

**EXCESS COST** 

LIABILITY

REMARKS

: AMP Authorised, 03 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER

LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER **ALLAN WU CLAIMS CONSULTANT**