

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Lim

Date: 01 Feb 2023

**Preliminary Advice**

Vehicle No	: S1980CD	Accident Date	: 17/01/2023
Make	: AUDI A4	Policy No.	: SP2002751854
Assignment Date	: 20/01/2023	Excess	: S\$600.00
Date of Inspection	: DESKTOP SURVEY	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOCARE CENTRE		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,853.10
Revised Amount	:S\$	16,004.50
Check Items (Estimated)	:S\$	7,996.30
Total	:S\$	24,000.80

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	37,000.00
COE / PARF Rebate	:S\$	3,000.00 (estimated)
Salvage Value	:S\$	
Margin for Repair	:S\$	34,000.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Part by part repair, according to repairer there is no 2nd hand parts available

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .