

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

TP A la.
Xiao by

9-Jan-23

JTFH202200243112

Our ref : TP/5216/22

HYS Tradins Service

RE : estimate cost for vehicle no : GBH 4729P

1 pc	lh headlamp	Ambed	\$	898.00	✓
1 pc	frt bumper	Distalnd.		595.00	✓
1 pc	frt bumper lh retainer	Engd		150.00	✓
1 pc	frt lh door	Distalnd		1,795.00	1445
2 pcs	frt lh door hinges	new		238.40	+
1 pc	frt lh step garnish	Distalnd		175.40	-
4 pcs	frt lh step garnish clips	new		20.00	-
1 pc	frt lh step panel	Distalnd	3542.50	91.00	✓
1 pc	frt bumper lh fog lamp cover	Delnd	2657.17	62.10	-
8 pcs	frt bumper clips	new		40.00	30
1 pc	frt bumper reinforcement	new		345.00	+
1 pc	frt lh door pillar	Reps		465.00	+
1 pc	frt bumper lh wire cover	Ambed		76.40	✓
1 pc	frt lh hup cap	new		185.00	+
				5,136.30	
				1,284.08	
				3,852.23	

less 25%

1 pc	body sticker	new
1 pc	frt bumper sticker	new
1 pc	frt lh door sticker	new

Panel beating.

Spray painting.

Wiring.

Transfer door parts.

Plus 8% GST

25.00	snett	✓
250.00	200.	
500.00	200.	
1,000.00	600	
1,000.00	700	
30.00	✓	
80.00	✓	
6,737.23		
538.97		
7,276.20		

SD : Seven thousand two hundred seventy-six & cents twenty only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
h/s 09/01/23

05 Days

total: 4492.17
h/s: 3.5K