

# COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

DATE: 19.01.2023

INSURANCE: ALLIANZ (L/S)

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHA2405C

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper <i>Sen ✓</i>	1		\$ 481.10
	Front Bumper Clips <i>MeL ✓</i>	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Moulding ?	1		\$ 368.50
	Front Bumper Side Brkt RH ?	1		\$ 35.00
	DayLight Grille RH ?	1		\$ 93.45
	Front Fender (Blue-Drive) RH <i>Nec ✓</i>	1		\$ 26.60
	Front Fender Shield RH <i>Sen R</i>	1		\$ 164.70
				\$ 1,191.35
				\$ 238.27
				\$ 953.08
	<b>Labour Charge</b>			
	Panel Beating			\$ 400.00
	Spray Painting			\$ 300.00
	Check Wirings			\$ 40.00
				\$ 740.00
				\$ 1,693.08

529.70  
1059.4

350 ✓  
300 ✓  
30

1103.76  
220.75  
= 883.0

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 ~~3~~ days

= 900

L/S

20/1/23

*[Signature]*  
1230pm

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Hyundai Ioniq