

SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199206653M

DATE: 08.02.2023
DAY : Wednesday

Workshop Accident Repair Estimate **FOR SURVEYOR ONLY**

ACCIDENT DATE: 17.01.2023 BUS REGISTRATION NUMBER: SBS6073D
ACCIDENT TIME: 21:55 HRS BUS TYPE (DD OR SD): SD
THIRD PARTY CLAIM AGAINST: GARBAGE TRUCK, XD6752T DATE of SURVEY: 27.01.2023

S/No	SECTION A :	PARTS & MATERIAL COST	
	SBS6073B, MB Citaro O530, SD, AC, 2 Axle.		
	Part or Item Description	Quantity	Total Cost
1	30600077 = OUTSIDE REARVIEW MIRROR;O/S	1 pc <i>Cra</i>	\$ 1,099.80
2	LAST ITEM		\$ -
3			\$ -
4			\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
TOTAL PARTS & MATERIAL COST			\$ 1,099.80

SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
FOR WORKSHOP ONLY.....		
Labour		\$ 244.40
Spray Painting		\$ -
Vinyl		\$ -
Advertisement		\$ -
Others:		\$ -
TOTAL LABOUR COST		\$ 244.40

SECTION C :	SUMMARY	
	TOTAL REPAIR COSTS	\$ 1,344.20
	TOTAL DOWNTIME	0.5 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

NOTE: Parts prices are subject to confirmation

1) Repair cost is excluding loss of use.

2) Additional parts might be required during the course of repair.

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$1,249.80

1/2 days