

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. PA/OD/0070/2023/GW Date 16-Feb-23 Service Advisor CHANG Pages 1 of 1 Regn No SLU 5639 Y Model No AUDI Q5 2.0 TFSI	
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW CHARGE AIR COOLER. S/N	\$ 480.00	
2	TO REPAIR RHS FRONT FENDER.	\$ 800.00	250
Parts			
1	CHARGE AIR COOLER 1	\$ 964.00	711.00
GRAND TOTAL		\$ 2,244.00	

For Premium Automobiles Pte Ltd

Rahul
 16/02/23



 Authorised Signature