

SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO.: /20230117/0509)	LOCATION OF FIRE: Open Space Car Park, Near to Block 544, Ang Mo Kio Avenue 10 Singapore 560544	
FIRE REPORTED ON: 17 Januar	ry 2023		
TIME OF CALL: 11:36:33 hrs			
STATION COVERAGE: Ang Mo Kio Fire St	ation		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The electrical wirings and components underneath the seat of a Sym motorcycle (FBH9676A) at car park lot no. 193.			
METHOD OF EXTINGUISHMENT: By a member of public using a dry powder fire extinguisher prior to the arrival of SCDF crew.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the electrical wirings / components underneath the seat)			
DAMAGE OBSERVED*: As a result of the fire, the electrical wirings and components underneath the seat of the motorcycle were damaged. Other parts of the motorcycle sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	NRIC/FIN		DEAD/INJURIES SUSTAINED
NIL	N	IL	NIL
REPORT ISSUED BY: FONG CHUN HERN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated report. No signature is required.

^{*}This is based on observations made by the fire investigator incidental to his/her investigation to determine the cause and origin of the fire, and is not to be taken as an exhaustive list of damage caused by the fire.