

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI23000794/Uvp3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	re: 07/02/2023	
			Cod	de: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJT 6603Y	Veh. Inspected	SBL 139Y	
	Policy No.	P10424937R02	Coverage (\$)	0.00	
	Claim No.	C10019909/CH	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	26/01/2023	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	MR2B23F3101122083	Colour	BROWN	
	Odometer	87518 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/60 R15	BRIDGESTONE	7 mm	
	L/H Front Tyre	195/60 R15	BRIDGESTONE	7 mm	
	R/H Rear Tyre	195/60 R15	BRIDGESTONE	7 mm	
	L/H Rear Tyre	195/60 R15	BRIDGESTONE	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	16/01/2023	Inspection Date	30/01/2023	
	Survey held at AUTO BAY@ KAKI BUKIT AVENUE 6 ENTRANCE 'A' #01-04				
	Repairer	·			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: