



SUPPLEMENTARY TO REPAIR

VEHICLE NO. : GBK 2650 D
 MAKE : TOYOTA
 MODEL : HIACE VAN URBO 5DR MT
 YEAR : 2019
 CHASSIS NO : JTFHT02P100250231

SURVEYOR NAME	:	
DATE OF SURVEY	:	
TIME OF SURVEY	:	

DATE : 10-Feb-23
 DATE OF ACCIDENT : 20-Jan-23
 THIRD PARTY REF : GBF 4035 T
 THIRD PARTY REF : SOMPO INS

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Tail lamp lower garnish				\$ <i>CM</i> 99.10
1 pc	Tail gate inner trim				\$ <i>Dol</i> 192.00
1 pc	Rear LH fender inner trim				\$ <i>CRZ</i> 160.40
	Less 25%				\$ 451.50
					\$ 112.88
					\$ 338.63
TG/ZX	TOTAL				\$ 338.63

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 675721
 Tel: 65-64520893 Fax: 65-64589127 Email: sales@lmtm.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd