Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 27 Jan 2023 Azlan, Syazairdina Date:

Preliminary Advice

Vehicle No : SKH6911J **Accident Date** : 17/01/2023 Policy No. Make : AUDI A3 SPORTBACK : 1900244032-01

Assignment Date : 27/01/2023 Excess : S\$0.00 Date of Inspection : 26/01/2023

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

55 UBI ROAD 1 SINGAPORE 408699 Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,636.00
Revised Amount	:S\$	3,515.00
Check Items (Estimated)	:S\$	446.00
Total	:S\$	3,961.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 108,000.00 COE / PARF Rebate 38,894.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 69,106.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ndly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to part prices and labour cost check.