



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22011741/Svy3-1~~  
CS3/LPC22011741/Svy3-1

Date: 22/11/2022

Code: LPC2

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	XD 9789T	Veh. Inspected	SMY 8539A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	<del>GERALD POH</del> Kenny Lim	Assign Date	<del>22/11/2022</del> 25/01/2023

#### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

#### 4. Description of Damages

--	--

#### 5. General Information

Accident Date	19/11/2022	Inspection Date	22/11/2022
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

#### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.