

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Tuesday, 31 January 2023 12:52 PM
To: Shiau Chan (LKKAuto)
Subject: Re: EQI-PRS SJN 3045J SURVEYED BY ARKID (OUR REF: CS3/EQI23000823/Wqp3)

Dear Shiau Chan,

Audit check done for SJN3045J, found COR range should be S\$3K to S\$3.8K with 4 repair days.

Best Regards,

Simon Ho
LKK Auto Consultants Pte Ltd
Phone: 6256-3561| email: simonho@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Tuesday, 31 January 2023 11:36 am
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: EQI-PRS SJN 3045J SURVEYED BY ARKID (OUR REF: CS3/EQI23000823/Wqp3)

Dear Simon,

For your audit.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)