



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. AC2302072
INV Date 04/04/2023
Reference CS3/III23000825/Tqp3m4
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMR 6567T
Insured Veh. SLV 1186H
Claim No.
Policy No. D21MFL0000447_02
Accident Date 20/01/2023
Inspection Date 30/01/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 30.01.2023 10.44am	
- Dismantle Inspection 31.01.2023 01.39pm	
- After Repair Inspection 03.02.2023 02.56pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML