

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation internationale Des Experts En Automobile					
	ECICS LTD		Ref:	CS/ICS23000826/Tvc	
	10 EUNOS ROAD SINGAPORE POS SINGAPORE 4086	T CENTRE #09-04A	Date	e: 27/01/2023	
			Cod	e: ICS	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKW 4787K	Veh. Inspected	SLM 8839J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	DMPC2300048H/02/CT	Excess (\$)	0.00	
	Assign From	CRYSTABELLE TAN	Assign Date	27/01/2023	
2. Vehicle Particulars & Condition					
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
5.	General Information				
	Accident Date	16/01/2023	Inspection Date	27/01/2023	
	Survey held at	BORNEO MOTORS (S) PTE LTD			
		2 PANDAN CRESCENT SINGAPORE 128462			
			marks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				