



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO23000833/Aqp3e2

Date: 20/06/2023

Code: SMO

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 9359B	Veh. Inspected	SKC 6716H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2300371/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	27/01/2023

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GB31036532	Colour	WHITE
Odometer	163702 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	26/01/2023	Inspection Date	30/01/2023
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------