

(SUPPLEMENTARY)

INSURER: ERGO Insurance Pte. Ltd. (HQ)

**PARTICULARS OF CLAIM**

|                               |                                 |                       |                   |
|-------------------------------|---------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                 | Ref. No:              | OD/012023/5940    |
| Policy No:                    | DMPG22013468                    | Date of Loss:         | 24/01/2023        |
| Vehicle Reg. No.:             | <b>SNE9552Y</b>                 | Driveable?            |                   |
| Driver Age/Info:              |                                 | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                              | Third Party Involved? | YES               |
| Insured/Claimant:             | TAY JUNJIE                      |                       |                   |
| Make/Model:                   | TOYOTA HARRIER, 2.0 M GRADE (A) | Vehicle Reg. Date:    | 30/09/2019        |
| Vehicle Colour:               | BLACK                           |                       |                   |
| Engine No:                    | 8ARZ165536                      | Chassis No:           | JTEZB3GH50J004887 |
| Odometer:                     | 48669 KM                        |                       |                   |
| Paint Type:                   |                                 |                       |                   |
| Total Loss?                   | <b>NO</b>                       |                       |                   |
| Est. Duration of Repair (day) | 8                               |                       |                   |
| Present Location:             | VIN'S MOTOR PTE LTD (SIN MING)  |                       |                   |

**COST OF CLAIMS**

|                                   | <b>Amount</b>    |
|-----------------------------------|------------------|
| Parts                             | 3,267.00         |
| Miscellaneous Items               | 0.00             |
| Labour                            | 180.00           |
| Paintwork Labour                  | 0.00             |
| Towing                            | 0.00             |
| <b>Gross Total (S\$)</b>          | <b>3,447.00</b>  |
| <b>+ GST 8.00% (S\$)</b>          | <b>275.76</b>    |
| <b>Nett Amount (S\$)</b>          | <b>3,722.76</b>  |
| <b>+ Previous Estimates (S\$)</b> | <b>18,795.24</b> |
| <b>Claim Total (S\$)</b>          | <b>22,518.00</b> |

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Feb 2023)  
**Parts:** M1-SUV TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** Vin's Motor Pte Ltd/SNE9552Y/01/02/2023 14:36  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                                  | %Disc | %Depr | Amount        |
|-----|-----|----------|----------------------------------------------|-------|-------|---------------|
| 1   | 1   |          | *BONNET CHROME MOULDING <i>monty broken</i>  | 0.00  | 0.00  | *250.00 F ✓   |
| 2   | 1   |          | *BONNET LOCK <i>1st</i>                      | 0.00  | 0.00  | *70.00 F ✓    |
| 3   | 1   |          | *FRONT SUPPORT PANEL <i>2nd</i>              | 0.00  | 0.00  | *650.00 F ✓   |
| 4   | 1   |          | *BRACE PANEL <i>1st</i>                      | 0.00  | 0.00  | *280.00 F ✓   |
| 5   | 1   |          | *AIRCON CONDENSER <i>1st</i>                 | 0.00  | 0.00  | *1,100.00 F ✓ |
| 6   | 1   |          | *INTER COOLER <i>1st</i>                     | 0.00  | 0.00  | *420.00 F ✓   |
| 7   | 1   |          | *RADIATOR TOP RH SIDE GUIDE <i>defunct</i>   | 0.00  | 0.00  | *50.00 F ✓    |
| 8   | 1   |          | *RADIATOR TOP LH SIDE GUIDE <i>defunct</i>   | 0.00  | 0.00  | *50.00 F ✓    |
| 9   | 1   |          | *RADIATOR LOWER RH SIDE GUIDE <i>defunct</i> | 0.00  | 0.00  | *50.00 F ✓    |
| 10  | 1   |          | *RADIATOR LOWER LH SIDE GUIDE <i>defunct</i> | 0.00  | 0.00  | *50.00 F ✓    |

F=Franchise part.

|                                            |                 |
|--------------------------------------------|-----------------|
| <b>Sub Total (\$\$)</b>                    | <b>2,970.00</b> |
| <b>+ Margin on L,N Items 10.00% (\$\$)</b> | <b>297.00</b>   |
| <b>Total Parts (\$\$)</b>                  | <b>3,267.00</b> |

Vin's Motor Pte Ltd/SNE9552Y/01/02/2023 14:36. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

*ym*  
*2kk And*  
*8*

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

| No                       | Particulars          | Lab.Type | Amount                  |
|--------------------------|----------------------|----------|-------------------------|
| <u>Labour Items</u>      |                      |          |                         |
| 1                        | TO REFILL AIRCON GAS | New      | <del>180.00</del> 120/- |
| Gross Labour Cost (\$\$) |                      |          | 180.00                  |

Vin's Motor Pte Ltd/SNE9552Y/01/02/2023 14:36. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS  
< END OF ESTIMATES >