



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23000852/Uvy3m4 Date: 14/02/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMU 5083M	Veh. Inspected	SMK 2759U	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0373	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	27/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS ALPHA HYBRID (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	ZVW400032059	Colour	SILVER	
Odometer	147214 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/50 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/01/2023	Inspection Date	30/01/2023	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)REGISTRATION DATE: 01 APR 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	