

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 08 Feb 2023

**Preliminary Advice**

|                    |                                                                                                      |                         |              |
|--------------------|------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GQ44B                                                                                              | Accident Date           | : 19/01/2023 |
| TP Vehicle No      | : GBG8316B                                                                                           | Assignment Date         | : 30/01/2023 |
| Make               | : FIAT DOBLO                                                                                         | Est. Duration of Repair | : 5          |
| Date of Inspection | : 30/01/2023                                                                                         |                         |              |
| Inspection At      | : VENDA ENGINEERING & TRADING PTE LTD (PIONEER)<br>NO. 8 TUAS AVENUE 18, LEVEL 3<br>SINGAPORE 638892 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 12,583.30 |
| Revised Amount              | :S\$ | 3,311.76  |
| Check Items (Estimated)     | :S\$ | 1,471.00  |
| Total                       | :S\$ | 4,782.76  |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.