(08/11/13) wef ASS. REC. BY: Marcus REF: Cay	ASM 23000873/Upa3		
ASSIGNMENT			
*	1 10 117787 20/ da		
From: Date:	Veh No: (1 SKSA / Yr Regn: 25/06/10) Type: M.Car / M.Cycle / Bus (Van/ Lorry / Taxi / Prime Mover /		
Estimated Cost:			
OD/TH/WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or A/		
To Inspect Vehicle No: 63143759	A/O Insured CAD MILANA		
at Workshop m/s	Colour Gray A/C: Insured / Std / NI / NA		
of SLF738G	Sp.Reading +4743 T/Radio: Insured / Std / NI / NA		
Insured: SPICES	Eng/No:		
Policy No.	C/No: VM20142430		
Claims No.	Gen. Cond Good / Fair / Poor / Burnt		
Sum Insured: Excess:	Steering: Mareter / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or		
Make of Veh: Modi: Nil/ S/Rim / STD A/Rim or			
Tyre Size: F: 175/70nl4			
(Policy Condition)	R:		
Remark: The veh had commenced its N/S			
repair at the time of inspection.	TOYO/YOKO or /copses		
Bal. or Market Value:	Front Rear		
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm		
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm		
Est. Repairs: 6 days Res.: Yes or No	D.O.A. 21(01(23) D.O. 27/7/23		
Lum Sum: % 3 Val.: Yes or No	Survey held at		
6	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or		
CA / REV / REP. / 24 HRS Vehicle: IN / OUT			
Date: Person Contacted: LTAGLOS36 The U/C / Chassis frame / Body Structure affected due to collision.			
Date / Time Action / Instruction Quality			
3/1/23 4/5\$ 7600 in hours Alen.			
	•		
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
1) : Final Report	Resurvey No. of Trip: Survey Fee:		
Date/Time, File Return to?	Transportation:		
2)	Add Fee:: Site Insp ()s+Rs,si		
	: Interview (\$) Photos		
Report Format :	: Tech. Invs (\$) Others		
Lump Sum / I.B.I: (\$: Weekend (\$		
	TOTAL		

Singapore 417883 Tel No: 67452063/67467158 Fax No: 67458520 Tax Reg No: 200006262D VEHICLE No: GBK 3759T **NETT ITEM** \$1,455.30 **REAR WINDSCREEN** 1PC \$110.10 REAR WINDSCREEN MOULDING 1PC 2/01.20 \$2,245.10 TAILGATE 1PC \$68.60 1PC TAILGATE REAR LOGO \$118.00 / 1PC TAILGATE 'NV 200 'EMBLEM Ner \$105.00 / TAILGATE 'VANETTE 'EMBLEM 1PC \$80.00 🗶 TAILGATE '600kg 'STICKER 11 1PC \$525.20 1PC TAILGATE INNER TRIM 408.20 17011 \$45.00 TAILGATE INNER TRIM CLIPS 1SET \$399.20 100/Jul 1PC TAILGATE INNER LOCK \$105.10 💢 TAILGATE INNER LOCK GARNISH 1PC 351.80 \$428.90 1PC TAILGATE OUTER HANDLE GARNISH Cne 101 \$335.80 TAILGATE WEATHERSTRIP 241.20 1PC 1WI \$60.00_ 1PC TAILGATE INNER CLOSING HANDLE \$576.00 TAILGATE DAMPERS @\$288.00 11 2PCS \$145.80 🗶 1PC TAILGATE REAR WIPER ARM 11 \$100.60 🗴 1PC TAILGATE REAR WIPER BLADE 11 11 \$625.60 × TAILGATE REAR WIPER MOTOR 1PC GO \$745.60 1PC 632.70 REAR BUMPER TOIN \$244.50 1PC **REAR BUMPER SPONGE** \$130.00 2PCS REAR BUMPER SIDE HOLDERS @\$65.00 nec \$39.00 REAR BUMPER CLIPS 1SET \$899.20 -1PC **REAR END PANEL OUTER** \$845.90 1PC REAR END PANEL INNER 501 182 \$285.00 / REAR END PANEL TOP GARNISH 1PC 1466.00 \$1,999.50 **REAR FLOOR PANEL** 1PC \$820.00 1PC REAR FLOOR PANEL TOP CARPET \$1,310.00 2PCS TAILLAMPS @\$655.00 \$1,370.00 🗶 2PCS TAILLAMP HOUSING PANELS @\$685.00 17 \$682.30 **REAR EXHAUST** 1PC \$50.00 🗶 1PC **RESR EXHAUST MOUNTING** 10 REAR SPARE TYRE BRACKET \$369.20 1PC 11 REAR FENDERS @\$1499.30 R \$2,998.60 🗸 2PCS \$20,318.10 S.NETT nu \$20.00 ,__ 1SET TAILGATE 70Km/h & 5 PAX STICKER \$40.00 1PC REAR WINDSCREEN SEALANT 111 \$30.00 1PC REAR WINDSCREEN INNER SEAL M \$200.00 X 1PC REAR WINDSCREEN SOLAR FILM

11

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

1SET 1SET 1PC 1PC 1PC	REAR REVERSE SENSOR REAR REVERSE CAMERA REAR LICENCE PLATE REAR FLOOR PANEL TOP WOODEN REAR END PANEL SEALANT	\$250.00 L 0 3 \$380.00 X \$50.00 X \$900.00 X \$50.00 3
	TO CHECK WIRING	\$50.00 20
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00 (10
	TO DISMANTLE & BREPLACED REAR WINDSCREEN	\$150.00 120
	TO DISMANTLE & REFIX GARNISH UPHOLSTERY	1へ \$120.00 ×
	TO TRANSFER TAILGATE MECHANISM	\$100.00 60
	TO DISMANTLE & REFIX REAR EXHAUST	J ↑ \$100.00 ×
	TO MOUNT VEHICLE ON CAR O-LINER	1 ↑ \$380.00 ×
	TO SPRAY RUST PROOFING	\$150.00 &
	LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00 /200
	TO PUTTY & SPRAY PAINTING	\$1,800.00 9,22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL

\$26,668.10

Acknowledged by Repairer

Signature:

Date: