

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI23000877/NVY3M4**Date:** 06/02/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000276	
<b>Claimant Vehicle No :</b>	SHA1790X	<b>Insured Vehicle No :</b>	SLQ5976U	
Date of Loss:	27/01/2023	Nature of Claim:	TP	Claim No: M2300667

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA1790X</b>		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU712700
Reg. Date:	22/12/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU097269
Colour:	Blue	Odometer:	0 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

**CONDITION OF TYRES**

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,210.64	3,933.92	276.72	6.57
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,600.00	1,130.00	470.00	29.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,821.64</b>	<b>5,074.92</b>	<b>746.72</b>	<b>12.83</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,050.00</b>		
<b>(\$\$)</b>	5,821.64	4,050.00	1,771.64	30.43
<b>+ GST 8.00/8.00% (\$\$)</b>	465.73	324.00	141.73	30.43
<b>Nett Amount (\$\$)</b>	<b>6,287.37</b>	<b>4,374.00</b>	<b>1,913.37</b>	<b>30.43</b>

**INSPECTION**

Date of Assignment:	30/01/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	31/01/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** Muhammad Nazril Bin Abdullah**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1790X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Cracked	1,052.20 FL	*1,052.20 FL
2	1		*FRT BUMPER GRILLE LH	Cracked	187.20 FL	*187.20 FL
3	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*HEADLAMP ASSY LH	Cracked	1,388.00 FL	*1,388.00 FL
5	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
6	1		*FRT FENDER LH	Dented	663.00 FL	*663.00 FL
7	1		*FRT FENDER SHIELD LH	Serviceable	174.90 FL	*- FL
8	1		*FRT FENDER AIR DUCT LH	Serviceable	126.20 FL	*- FL
9	1		*FRT BUMPER SIDE BRACKET LH	Serviceable	44.80 FL	*- FL
10	1		*ADVERTISEMENT - FRONT FENDER	Necessary	100.00 F	*100.00 F
					Sub Total (S\$)	5,238.30 4,892.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,027.66 958.48
					Total Parts (S\$)	4,210.64 3,933.92

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	560.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
Gross Labour Cost (\$\$)			1,600.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >