




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS3/ASM23000885/Wvp3m4 Date: 07/02/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 4627R	Veh. Inspected	SMF 4509M
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S3M04IHP	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	30/01/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FREED HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GB71077455	Colour	BLACK
	Odometer	288277 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	CONTINENTAL	5 mm
	L/H Front Tyre	185/65 R15	CONTINENTAL	5 mm
	R/H Rear Tyre	185/65 R15	KAPSEN	6 mm
	L/H Rear Tyre	185/65 R15	KAPSEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information				
	Accident Date	26/01/2023	Inspect Date / Time	30/01/2023 (03:00 PM)
	Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM23000885/Wvp3m4

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.