

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL INV No. AC2302075

64 CECIL STREET INV Date 04/04/2023

#05-02 IOB BUILDING Reference CS3/GRB23000893/Uya3e2 SINGAPORE 049711 CDP

Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SKV 6969U

Insured Veh. SLQ 3760M

Claim No. MFL2023D0001668

Policy No. D21MFL0000447_02

Accident Date 23/01/2023

Inspection Date 30/01/2023

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 30.01.2023 03.03pm	
- Dismantle Inspection 13.02.2023 12.03pm	
Merimen Fee	11.00
Subtotal	131.00
GST (8%)	10.48
Grand Total	141.48

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM