(08/11/13) wet ASS. REC. BY: MC/CLS REF: CS/SN	1023000894/4943						
	ASSIGNMENT						
From: Date:	Veh No: GBA7557k Yr Regn: 27/10/07 Type: M.Car / M.Cycle / Bus / Van (Corry / Taxi / Prime Mover /						
Estimated Cost: OD (TP)/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (M)						
To Inspect Vehicle No: GBA 7587K	Make: Toysto Dyna c.c 2982						
	Colour Silver A/C: Insured / Std / NI / NA						
at Workshop m/s	Sp.Reading 229325 T/Radio: Insured / Std / NI / NA						
Insured:	Eng/No:						
Policy No.	C/No: JTFAT 35 Y 30 300 1550						
Claims No.	Gen. Cond: Godd / Fair / Poor / Burnt						
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or						
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or						
Make of Veh:	Modi: (Nil) S/Rim / STD A/Rim or						
	Tyre Size: F: / &G- NJG-						
(Policy Condition)	R: 15-5-12 FALKEN						
Remark: The veh had commenced its N/S	O/S BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /						
repair at the time of inspection.	TOYO/YOKO or						
Bal. or Market Value:	Front Rear 6/1						
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 0 mm R/Bal. 0 mm						
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 0/6 mm						
Est. Repairs: 2 days Res.: Yes or No	D.O.A. 18/01/23 D.O.I. 30/01/23						
Lum Sum: % 3 Val.: Yes or No	Survey held at						
CA / REV / REP. / 24 HRS C 9196 IN	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or						
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.						
Date / Time Action / Instruction Day 1 (K. Coeuntil 31-10-2027 1 14) to: Ilay ols crocked // 1/3 1/5 \$ 600 indend	El-a (Red, \$ 6330, 91%)						
Date/Time, File Pass to? 1) 20/2/23 : Preli. Report 1) 20/2/23 : Final Report Date/Time, File Return to?	Days Of Repair: 2 Resurvey No. of Trip: / Survey Fee: Transportation: d Fee: : Site Insp (\$)S+RS,SI						
2)	: Interview (\$) Photos						
Bound Format : TP	: Tech. Invs (\$) Others						
Report Format : Lump Sum / I.B.I: (\$ 600	: Weekend (\$						
Lump Sum / I.B.I: (\$ 600	, vveckend (+						

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle No.: ehicle to be Exported:	Company 919H GBA7557K				
Vehicle Details Vehicle No.: Vehicle to be Exported:	GBA7557K				
Vehicle to be Exported:					
	No				
	No				
ntended Deregistration Date:	30 Jan 2023				
Vehicle Make:	TOYOTA				
/ehicle Model:	DYNA 150 MANUAL				
Primary Colour:	Silver				
Manufacturing Year:	2007				
Engine No.:	1KD1723293				
Chassis No.:	JTFAT35Y303001550				
Maximum Power Output:	-				
Open Market Value:	\$24,285.00				
Original Registration Date:	27 Dec 2007				
First Registration Date:	27 Dec 2007				
ransfer Count:	2				
Actual ARF Paid:	\$0.00				
ntended PARF Rebate Details					
ARF Eligibility:	No				
ARF Eligibility Expiry Date:	·-				
PARF Rebate Amount:	\$0.00				
ntended COE Rebate Details					
COE Expiry Date:	31 Oct 2027				
COE Category:	C - Goods Vehicle & Bus				
OE Period(Years):	5				
QP Paid:	\$29,672.00				
OE Rebate Amount:	\$28,204.00				
otal Rebate Amount: ¶essage	\$28,204.00				
lease note that all future COE renewals for thi ubject to the statutory lifespan (if applicable) o					

The information contained herein is correct as at 30 Jan 2023

OK

sgcarmart

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

① X

Resources

Pneumatic connectors

Open

Post an Advertisement Sell it yourself! Advertise it at just \$68 until it's SOLD!

Advertiser Login

Ways of Selling

Mercedes-Benz CLA-Class CLA250 AMG Line Premium Pl...

Full Carbon Fibre Interior With Cla45s Bodykit.

Direct Owner StarAd



3 vehicles

Post an Ad

TOYOTA DYNA 2027

Any Category

Advanced Search

Search

Make Model

Price Depreciation Reg Date

Veh Type Status

Search Selection

TOYOTA DYNA 2027

till 12/2027)

\$58,800

old 18-Jan-2013

Απν 2,982 cc

Eng Cap

Anv 58,218 km Anv

Sort by Date Posted V 20 V results/page

Available

Available

Fuel Type: Diesel

Genuine super low mileage! One owner! Seldom used! New seat cushion and paintwork. Very well maintained and reliable. Newly releas...

\$11,950 /vr

Posted: 26-Jan-2023

Toyota Dyna 150 3.0M (COE till 07/2027)

Toyota Dyna 150 3.0M (COE

\$55,800

\$12.550 /vr

12-Jul-2012

2.982 cc

Available

Fuel Type: Diesel

Renew COE Toyota Dyna 3.0m. Powerful diesel engine, new paint work done with cabin height box. High trade-in and flexible in-house I...

Posted: 19-Jan-2023



Toyota Dyna 150 3.0M (COE till 08/2027)

\$54,800

\$11,950 /yr

20-Nov-2012

2,982 cc

180,582 km

Available

Fuel Type: Diesel

Newly Renewed 5 Years COE, Can Further Renew Another 5 Years In Future. Good Investment. Low Installment. Low Depreciation. Reli...

Posted: 12-Dec-2022

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 v results/page

Buy / Rent Cars

New Cars For Sale

Used Cars For Sale

Cars For Rent

Sell Your Car

Post an Ad

Sell by Bidding

Sell by Consignment Aftermarket



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

18TH JANUARY 2023

30th January 2023

OWNER:

D.O.A:

OCL BUILDING SERVICES PTE LTD

REG. NO.:

GBA 7557 K

MAKE/MODEL: TOYOTA DYNA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

	REPAIR COST FOR THE VEHICLE MENTIONED AB	OVE				
QTY	DESCRIPTION			AMOUNT(S\$)		
	<u>LIST ITEMS</u>					
	1 Rear Tailgate			\$	11	1,945.20 🗶
	2 Rear Tailgate Latch			\$	MR	390.00
	2 Rear Tailgate Side Member with Rubber			\$	2	536.00 ×
	2 Rear Tailgate Hinges			\$	1	136.00
	1 Rear Tailgate Lower Member	2 - 2		\$, R	749.40 🎗
	2 Rear Taillamps	01.386	Msnn	\$ 3	scre	750.00 (2)
	2 Rear Taillamp Brackets			\$	11	238.40
	1 Rear Number Plate Bracket			\$	11	155.00
	1 Rear Number Lamp			\$	17	175.00
	1 Rear Tire Carrier			\$	17	385.00 🗶
					2000	A2
				\$		5,460.00
			LESS 25%	\$		1,365.00
				\$		4,095.00
	SPECIAL NETT ITEMS					
	1 Rear "13PAX" Sticker			\$	17	35.00 💉
	1 Rear "70KM/H" Sticker			\$	17	35.00
	1 Reverse Sensor			\$	21	280.00 >
	1 Rear Number Plate			\$	Bert	35.00 20
					320	20
				\$		385.00
S/N	LABOUR CHARGES					
1	To remove, replace & check up wiring			\$		50.00 Zn
3	To rust proof affected areas			\$	11	0
9	Panel Beating			\$		1,200.00 300
10	To re-spray the affected areas			\$		1,000.00 200
						~00

2,450.00 6,930.00

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company