

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT23000222	Page	1
Registration No	: SJN6655D	Date	: 26. Jan 2023		
Chassis No	: JHMRC1890MC202926	Customer No.	: WZL009		
Model	: ODYSSEY 2.4 EXV-S 21YM (EURO 6)	Svc Advisor	: NG SIN HAI		
Owner's Name	: YU HUI PING DORIS	Engine No	: K24W72540486		
Ins Policy No.	:	Date Time	: 26. Jan 2023 6:37:31 PM		
Date of Accident	: 26/1/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.60	48.60
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.30	31.10
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	1.01	13.61
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.23	3.15
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.55	7.37
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.31	4.21
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	9.60	129.60
68100-T6A-Q10ZZ	TAILGATE COMP	1	1146.20	25	859.65	68.77	928.42
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.70	25	94.27	7.54	101.81
75701-T6A-000	EMBLEMH	1	28.20	25	21.15	1.69	22.84
75722-T6A-901	EMBLEM,RR.	1	33.20	25	24.90	1.99	26.89
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER	1	562.00	25	421.50	33.72	455.22
71593-T6A-003	SPACERRR.BUMPER SIDE	1	20.40	25	15.30	1.22	16.52
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.22	16.52
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.97	13.04
66100-T6A-Q01ZZ	PANEL COMP,REAR	1	493.20	25	369.90	29.59	399.49
04636-T6A-J22ZZ	PANEL SET,R.RR.OUTSIDE	1	1001.10	25	750.82	60.07	810.89

Printed on 26/1/2023 6:46:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT23000222	Page	2
Registration No	: SJN6655D	Date	: 26. Jan 2023		
Chassis No	: JHMRC1890MC202926	Customer No.	: WZL009		
Model	: ODYSSEY 2.4 EXV-S 21YM (EURO 6)	Svc Advisor	: NG SIN HAI		
Owner's Name	: YU HUI PING DORIS	Engine No	: K24W72540486		
Ins Policy No.	:	Date Time	: 26. Jan 2023 6:37:31 PM		
Date of Accident	: 26/1/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount Incl GST
04646-T6A-J22ZZ	PANEL SET,L.RR.OUTER	1	1001.10	25	750.82	60.07	810.89
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	361.70	25	271.27	21.70	292.97
34150-T6A-J51	LIGHT ASSY,R.LID	1	413.40	25	310.05	24.80	334.85
34155-T6A-J51	LIGHT ASSY,L.LID	1	381.90	25	286.42	22.91	309.33
33500-T6A-J51	LIGHT ASSY,R.TAIL	1	897.20	25	672.90	53.83	726.73
33550-T6A-J51	LIGHT ASSY,L.TAIL	1	897.20	25	672.90	53.83	726.73
39683-T6A-N11ZB	RETAINER,PARKING	4	44.70	25	134.10	10.73	144.83
39680-T0A-R12A4	SENSOR ASSY,PARKING BACK SENSOR	4	286.70	25	860.10	68.81	928.91
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	110.90	25	83.17	6.65	89.82
Sum Item					6873.77	549.89	7,423.66
BOSUN	SUNDRIES	1	110.00		110.00	8.80	118.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	20.00	270.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	20.00	270.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	120.00		120.00	9.60	129.60
BOJSE	BODY JOINT SEALANT END PANEL	1	120.00		120.00	9.60	129.60
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	120.00		120.00	9.60	129.60
BOBC	BODY UNDERSIDE COATING (N)	1	520.00		520.00	41.60	561.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00		520.00	41.60	561.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00		650.00	52.00	702.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00		650.00	52.00	702.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	52.00	702.00
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00		120.00	9.60	129.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	52.00	702.00
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	5000.00		5000.00	400.00	5400.00

Printed on 26/1/2023 6:46:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co., Sdn. Bhd., it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT23000222	Page	3
Registration No	: SJN6655D	Date	: 26. Jan 2023		
Chassis No	: JHMRC1890MC202926	Customer No.	: WZL009		
Model	: ODYSSEY 2.4 EXV-S 21YM (EURO 6)	Svc Advisor	: NG SIN HAI		
Owner's Name	: YU HUI PING DORIS	Engine No	: K24W72540486		
Ins Policy No.	:	Date Time	: 26. Jan 2023 6:37:31 PM		
Date of Accident	: 26/1/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	320.00	4320.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00		650.00	52.00	702.00
BC05R	TO PERFORM / RESET HONDA SENSING SYSTEM	1	650.00		650.00	52.00	702.00
BOSUN	REMOVE, RE-INSTALL, RE-ALIGN AND RESET AUTO TAILGA	1	650.00		650.00	52.00	702.00
Sum Labor					16330.00	1,306.40	17,636.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 23,203.77 1,856.29 25,060.06**Total (Inclusive of GST)** **25,060.06****Printed on 26/1/2023 6:46:55 PM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	26/01/2023 18:36 (SGT)
Reported by	Both
Date of Accident	26/01/2023 07:42 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	UPPER THOMSON ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN6655D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YU HUI PING DORIS
NRIC No	SXXXX868I
Email Address	DYU060811@GMAIL.COM
Mobile Phone No	(Phone) +65-98639356
Alternative Phone No	

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2400

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	3

DRIVER

Name of Driver	YU HUI PING DORIS
NRIC No	SXXXX868I
Date Of Birth	23/11/1977
Occupation	Indoor

Date Of Driving Pass	27/02/1998
Driving experience	24 YEARS AND 11 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98639356
Alt. Phone Number	-
Email Address	DYU060811@GMAIL.COM
Address	S
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	YEE CHIN PENG
Gender	Male

PASSENGER 2

Name	ROWELL YEE YIK HIN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX3639D
Vehicle Manufacturer	
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	
Address	
Address complement	
Postcode	
Insurance Company Name	
Nature Of Damage	
Details of property damaged in accident	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident


On 26 Jan 23, around 740 am, I was driving my car (SSN 6655 D) from Upper Thomson Road towards the direction of Marymount Lane / Bishan Street 21. At the traffic junction about to right turn my vehicle into Marymount Lane / Bishan Street 21 where I had stopped the car, I heard a loud screech sound followed by a loud bang to the rear of my car. I realised a medium size pickup lorry (BX 36390) had hit my car from the rear. My husband who was seated at the rear passenger seat went out to check what happened. We saw that the lorry had stopped at a direction opposite to the flow of traffic right beside us. The driver of the pickup lorry told my husband that he was (Khia Maung Aung 529515172) trying to avoid another car just now hence skidded. As none of us were injured, we took down each other's particulars then went on our respective journey.

Declaration

We declare the foregoing particulars are true in every respect.

 26/1/23
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

