



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 21/01/2023
VEHICLE : SNF1790Z
MAKE & MODEL : HONDA VEZEL
INSURANCE : ALLIANZ INSURANCE
SURVEYOR : LKK AUTO

PARTS		AMOUNT
1.	BONNET <i>Beater</i> ✓	\$ 900
2.	BONNET HINGE – LEFT & RIGHT <i>Beater</i> ✓	\$ 200
3.	FRONT BUMPER <i>Deled</i> ✓	\$ 780
4.	FRONT BUMPER TOP COVER - 2PCS <i>Deled</i> ✓	\$ 210
5.	FRONT BUMPER BRACKET – LEFT & RIGHT <i>2nd</i> ✓	\$ 100
6.	FRONT BUMPER GRILLE <i>Deled</i> ✓	\$ 480
7.	FRONT BUMPER LOWER GRILLE <i>Deled</i> ✓	\$ 290
8.	FRONT BUMPER LOWER LIPS <i>Deled</i> ✓	\$ 310
9.	HEADLAMP - LEFT <i>Canled</i> ✓	\$ 1980
10.	HEADLAMP - RIGHT <i>Canled</i> ✓	\$ 1980
11.	HEADLAMP LOWER BRACKET – LEFT & RIGHT ? ?	\$ 200
12.	FRONT SUPPORT BEAM <i>Beater</i> ✓	\$ 700
13.	FRONT SUPPORT PANEL <i>Beater</i> +	\$ 500



JACK CARS

DRIVE WITH ASSURANCE

14.	FAN MOTOR – LEFT & RIGHT	?	?	\$ 750
15.	FAN COVER – LEFT & RIGHT	?	?	\$ 320
16.	FAN FIN – LEFT & RIGHT	?	?	\$ 220
17.	CONDENSOR	Dented	✓	\$ 800
18.	RADIATOR	?	?	\$ 780
19.	WIPER TANK	?	?	\$ 150
20.	HORN – LEFT & RIGHT	?	?	\$ 300
21.	FOG LAMP – LEFT & RIGHT	?	?	\$ 500
22.	FRONT FENDER - LEFT	2 Buckled	✓	\$ 650
23.	FRONT FENDER - RIGHT		✓	\$ 650
SPECIAL NETT				
1.	FRONT NUMBER PLATE & COVER	cut d	✓	\$ 65
2.	CLIPS , RIVETS & SCREWS	new	30	\$ 100
3.	FRONT PARKING SENSOR (4 PCS)	new	+	\$ 320
4.	OUTSIDE TEMP SENSOR	?		\$ 280
5.	"HONDA" EMBLEM	new	✓	\$ 95
6.	COOLANT	new	50	\$ 100
7.	AIRCON GAS	new	40	\$ 150
8.	WIPER TANK FLUID	new	+	\$ 55
9.	TOW HOOK COVER	DeP	✓	\$ 75



JACK CARS

DRIVE WITH ASSURANCE

	LABOUR	
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA <i>800</i>	\$ 2500
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS. <i>800</i>	\$ 2000
3.	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE <i>30</i>	\$ 150
4.	TO REMOVE & REINSTALL SENSORS <i>50</i>	\$ 200
5.	ANTI RUST TREATMENT <i>60</i>	\$ 200
	PARTS + 10%:	\$ 15,125
	SPECIAL NETT :	\$ 1,240
	LABOUR :	\$ 5,050
	TOTAL :	\$ 21,415
	8% GST :	\$ 1,713.20
	GRAND TOTAL :	\$ 23,128.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adm L;
P/P 01/02/23
Not Authorised
ob Page