Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Tan Siok Thiew Jas Date: 21 Apr 2023

Preliminary Advice

Insured Vehicle No : GBD1999S

TP Vehicle No : SFC201A : 14/01/2023 Accident Date Make : SUBARU FORESTER Assignment Date : 31/01/2023

Date of Inspection : 01/02/2023 Est. Duration of Repair : 7

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

> 205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,673.60		
Revised Amount	:S\$	7,416.28		
Check Items (Estimated)	:S\$	0.00		
Total	:S\$	7,416.28		
Lump Sum Repair	:S\$	5,800.00		

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	lly
	let us have your authorisation.	

	uneconomical to b				

Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.