

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INCOME INSURAN	ICE LTD	R	Ref:	CS/INC23000967/Tvp3	
	75 BRAS BASAH R	D	ate:	31/01/2023		
	ATTN: DAVID PHU	A	C	ode:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLB 3398E	Veh. Inspected		PC 7050D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1205240-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		31/01/2023	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	12/01/2023	Inspection Date		01/02/2023	
	Survey held at	60 LAM HUAT #02-32 SINGAPORE 737869				
	Repairer	THINK ONE AUTOCARE PTE LTD				
5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						