



Tan Swee Lin Sharon
763, Ang Mo Kio Avenue 2,
Singapore 567793

Attention: Owner
Contact: 93377366

COMPLETE VMS PTE LTD
176 Sin Ming Drive, #03-14 / 07, Sin Ming Autocare, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

The Premier One Stop Vehicle Accident Claims Centre

SUPPLEMENTARY ES 010370-1

Date 20/4/2021
Vehicle Number SKU6414J
Make / Model TOYOTA HARRIER PREMIUM HYBRID 2.5
Engine Number 2AR1233960
Chassis Number AVU650024447
Accident_Date 26 Jan 2023
Policy Number 10607672

Description	Qty	Unit Price	Amount
-------------	-----	------------	--------

Parts

List Items

Rear End Panel Immobilizer Antenna	371.50	Shon 1	\$425.80	\$319.35 ✓
		Discount 25% applied		\$319.35
		Total		\$319.35

COMPLETE VMS PTE LTD

This is only an estimate base on our preliminary inspection and does not cover additional parts and labour time which may be require after the work has begin