

**CARWORKZ SG PTE LTD**

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645

H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua)

Co. Reg. No: 202039874Z GST No: 202039874Z

Email: carworkzws@gmail.com

ESTIMATED REPAIR COST DETAILS**ACC-23-0006**

To: INCOME INSURANCE LIMITED
75 BRAS BASAH ROAD
SINGAPORE 189557

Date: 30/01/2023
Vehicle No.: FBQ-6681-G
Make: PIAGGIO
Model: MEDLEY 150 ABS

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	HANDLE BAR	\$255.60	? ✓ ht / 150
1	HANDLE BALANCER LH	\$114.80	ant -
1	HANDLE BALANCER RH	\$114.80	? ✓ ant - 50
1	MIRROR LH	\$166.80	ant -
1	MIRROR RH	\$166.80	? ✓ ant -
1	BRAKE LEVER LH	\$122.40	ht - 80
1	BRAKE LEVER RH	\$122.40	? ✓ ant - 60
1	HEADLAMP ASSY	\$1,498.80	ant - 720
1	FRONT COWLING	\$398.40	ant - 298
1	FRONT SIDE COWLING LH	\$416.40	ant - 316
1	FRONT SIDE COWLING RH	\$416.40	? ✓ ant - 316
1	FORK ASSY LH	\$777.80	? ✓ } local repair.
1	FORK ASSY RH	\$777.80	? ✓ } CN120
1	FORK UNDERBRACKET	\$925.20	? ✓ nn.
1	STEERING BEARING KIT	\$223.20	? ✓ nn / 120
1	FRONT WHEEL	\$985.20	X nn
1	FRONT WHEEL SHAFT	\$98.40	? ✓ nn.
1	FRONT BRAKE PAD	\$108.60	X nn.
1	FRONT BRAKE DISC	\$201.40	? ✓ nn.
1	FRONT FENDER	\$238.80	ant -
1	FLOORBOARD LH	\$289.20	ant -
1	FLOORBOARD RH	\$289.20	? ✓ dis -
1	LOWER COVER LH	\$333.60	ant - 230
1	LOWER COVER RH	\$333.60	? ✓ dl / 230
1	SIDE STAND	\$117.60	ht -

**CARWORKZ SG PTE LTD**

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645

H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua)

Co. Reg. No: 202039874Z GST No: 202039874Z

Email: carworkzws@gmail.com

ESTIMATED REPAIR COST DETAILS**ACC-23-0006**

1	MAIN STAND	\$412.80	dd - 200
1	REAR FOORREST LH	\$186.20	dd - 120
1	REAR FOOTREST BRACKET LH	\$85.40	? X nn
1	REAR FOOTREST RH	\$186.20	cut - 120
1	REAR FOOTREST BRACKET RH	\$85.40	X nn
1	SIDE COVER, REAR LH	\$494.40	cut -
1	SIDE COVER, REAR RH	\$494.40	Ry
1	EMBLEM, SIDE COVER REAR LH	\$103.20	re -
1	EMBLEM, SIDE COVER REAR RH	\$103.20	re -
1	ENGINE COVER, REAR LH	\$265.20	dd -
1	ENGINE COVER, FRONT LH	\$214.80	1? X nn
1	PIAGGIO COVER, ENGINE LH	\$90.00	? X nn
1	PIAGGIO COVER, ENGINE RH	\$90.00	? X nn
1	AIR BOX COVER COMPLETE	\$381.60	cut - 250
1	REAR SHOCK ABSORBER LH	\$758.40	X nn
1	REAR SHOCK ABSORBER RH	\$758.40	X nn
1	REAR WHEEL ASSY	\$1,012.80	? X nn
1	REAR HUGGER	\$373.20	? X nn
1	EXHAUST PIPE ASSY	\$1,838.40	bt - 850
1	EXHAUST PROTECTOR, FRONT	\$109.20	cut -
1	EXHAUST PROTECTOR, REAR	\$117.60	cut -
1	SIDE COVER, REAR LOWER LH	\$98.40	cut -
1	SIDE COVER, REAR LOWER RH	\$98.40	X nn
1	RADIATOR	\$685.00	del - 485
1	RADIATOR COVER	\$138.00	mis -
1	BOX CARRIER	\$478.80	X
1	CAMSHAFT	\$186.20	X
1	MAGNETO	\$260.40	X
1	MAGNETIC COIL	\$110.20	X
1	CONROD	\$296.50	X
1	ENGINE GASKET	\$86.70	X
1	FRONT BRAKE SWITCH (Meady Buy)	\$58.70	X ✓ ds -

7651.30
6886.17

**CARWORKZ SG PTE LTD**

10 SIN MING IND EST SECTOR C, #01-06, SINGAPORE 575645

H/p: 81184734 (Soon Ng) / 98766876 (Anna Chua)

Co. Reg. No: 202039874Z GST No: 202039874Z

Email: carworkzws@gmail.com

ESTIMATED REPAIR COST DETAILS

ACC-23-0006

Sub Total	\$20,151.30
Discount 10% on Parts	(\$2,015.13)
	\$18,136.17

Special Nett

1 FRONT TYRE 100/80R16	\$150.00	x nn
1 REAR TYRE 120/80R14	\$180.00	x nn
1 FRONT NUMBER PLATE	\$30.00	rel
1 REAR NUMBER PLATE	\$30.00	del
1 GIVI TOP BOX	\$380.00	ant 280
1 BATTERY - NEED REPLACE AFTER CANNOT START (Already Buy)	\$80.00	? photo. ✓ ann
1 COOLANT	\$20.00	rel
1 GRAB WARMER BAG	\$90.00	ant
1 TOWING FEE (CNY SEASON)	\$60.00	x nn: towing LOD receipt 450
Sub Total	\$1,020.00	

Labour & Misc

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$600.00	300
TO CONDUCT FORK ALIGNMENT -10%	\$120.00	? ✓
TO RECONNECT ALL WIRINGS	\$50.00	30
TO CONDUCT ENGINE OVERHAUL	\$400.00	? x nn
TO REMOVE, REFIT EXHAUST & GASKET	\$80.00	? ✓ 40
TO PERFORM ELECTRICAL CHECK	\$30.00	x nn
TO REMOVE, REPLACE REAR SHOCK ABSORBERS	\$80.00	? 60 x nn
TO REMOVE, REFIT, BALANCE REAR WHEEL & TYRE	\$80.00	? 50 x nn
REMOVE & REFIX RADIATOR	\$80.00	40 ✓ 530
Sub Total	\$1,520.00	

Tanjim 97495749 / 62563561
31/3/23 @ 2:05 pm
L/S Resum after repair
Tanjim @ lkhant.com
4 days

Sub Total \$20,676.17
GST 8% \$1,654.09
Total \$22,330.26

Repair Unit \$4500
L/S \$4500, 4 days

6886.17
450
530
7866.17