

ASS. REC. BY:

REF: INC1Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8103k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4-5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF 3859 JYr Regn: 11.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MIT Outlanderc.c. 1998Colour: M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 61668

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GIF 7W

0600246

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / VRIM orTyre Size: F: Hapen 225/55R18R: TOYO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 4 mmL/Bal. 6 mmL/Bal. 4 mmD.O.A. 20/1/23D.O.I. 31/1/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chasals frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Data/Time, File Pass to?



: Prell. Report

1)

Data/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Transportation

S - RS - SI

: Fines

: Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6467 5788 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : INCOME INSURANCE LIMITED
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

Estimate No: ES2300009

Date: 30 Jan 2023

Policy No:

Veh Reg No: SMF3859J

Make/Model: MITSUBISHI
OUTLANDER 2.0 CVT

Chassis No: GF7W0600246

Engine No: 4J11AA1411

Reg. Date: 08/11/2018

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 20/01/2023

TP Veh Reg No: SMC3138Y

Estimate Repair Cost to Vehicle No :SMF3859J

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR WINDSCREEN SEALANT	60.00	1 PC	60.00	60.00
2 REAR NUMBER PLATE	60.00	1 PC	60.00	60.00
			120.00	120.00
Spare Parts				
3 REAR BUMPER	1,280.20	1 PC	1,280.20	1,280.20
4 REAR BUMPER BRACKET - LH	145.00	1 PC	145.00	145.00
5 REAR BUMPER BRACKET - RH	145.00	1 PC	145.00	145.00
6 REAR BUMPER GARNISH (CENTER)	595.20	1 PC	595.20	595.20
7 REAR BUZZER SENSOR	265.20	1 PC	265.20	265.20
8 REAR BUMPER SIDE RETAINER - LH	95.00	1 PC	95.00	95.00
9 REAR BUMPER SIDE RETAINER - RH	95.00	1 PC	95.00	95.00
10 REAR BUMPER LOWER GARNISH (SILVER)	585.70	1 PC	585.70	585.70
11 REAR BUMPER REFLECTOR - LH	245.10	1 PC	245.10	245.10
12 REAR BUMPER REFLECTOR - RH	245.10	1 PC	245.10	245.10
13 REAR BUMPER CLIPS	80.00	1 SET	80.00	80.00
14 REAR BODY END PANEL	879.10	1 PC	879.10	879.10
15 REAR BODY PANEL TOP GARNISH	298.50	1 PC	298.50	298.50
16 REAR TAILGATE	2,289.70	1 PC	2,289.70	2,289.70
17 REAR TAILGATE WEATHERSTRIP	185.90	1 PC	185.90	185.90
18 REAR TAILGATE LOCK	485.10	1 PC	485.10	485.10
19 REAR TAILGATE OUTER GARNISH	498.50	1 PC	498.50	498.50
20 REAR TAILGATE 'LOGO' EMBLEM	102.00	1 PC	102.00	102.00
21 REAR TAILGATE 'OUTLANDER' EMBLEM	103.20	1 PC	103.20	103.20
22 REAR TAILGATE 'MIVEC' EMBLEM	95.10	1 PC	95.10	95.10
23 REAR TAILGATE ABSORBER - LH	315.00	1 PC	315.00	315.00
24 REAR TAILGATE ABSORBER - RH	315.00	1 PC	315.00	315.00
25 REAR TAILGATE INNER TRIMBOARD	525.60	1 PC	525.60	525.60
26 REAR TAILGATE REFLECTOR - LH	475.10	1 PC	475.10	475.10
27 REAR TAILGATE REFLECTOR - RH	475.10	1 PC	475.10	475.10
28 REAR WIPER MOTOR	525.60	1 PC	525.60	525.60
29 REAR WINDSCREEN MOULDING	126.60	1 PC	126.60	126.60
30 TAIL LAMP LH	825.10	1 PC	825.10	825.10
31 TAIL LAMP RH	825.10	1 PC	825.10	825.10
32 SPARE WHEEL PANEL TOP COVER	255.00	1 PC	255.00	255.00
33 EXHAUST MUFFLER	1,286.30	1 PC	1,286.30	1,286.30

108

23



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : INCOME INSURANCE LIMITED
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 20/01/2023
TP Veh Reg No: SMC3138Y

Estimate No: ES2300009
Date: 30 Jan 2023
Policy No:
Veh Reg No: SMF3859J
Make/Model: MITSUBISHI
OUTLANDER 2.0 CVT
Chassis No: GF7W0600246
Engine No: 4J11AA1411
Reg. Date: 08/11/2018

Estimate Repair Cost to Vehicle No :SMF3859J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			14,663.10	14,663.10
Labour				
34 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600.00	1 JOB	1,600.00	?
35 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	600
36 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	?
37 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	1200
38 TO REMOVE/REFIT REAR COMPARTMENT GARNISH TO FACILITATE REPAIRS.	250.00	1 JOB	250.00	600
39 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	150.00	1 PC	150.00	600
40 TO REMOVE/RENEW REVERSE SENSOR.	150.00	1 JOB	150.00	500
41 TO REMOVE/RENEW EXHAUST MUFFLER.	200.00	1 JOB	200.00	X
42 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	200
			4,350.00	4,350.00
Total				SS 19,133.10
Add GST @ 8%				1,530.65
Total Amount Payable				SS 20,663.75

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SIX HUNDRED SIXTY THREE AND CENTS SEVENTY FIVE ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/01/2023 14:58 (SGT)
Reported by	Both
Date of Accident	20/01/2023 17:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	WOODLANDS CROSSING TOWARDS WOODLANDS CIQ
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMF3859J

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	JEFFERY YAP CHOON MING
NRIC No	S7178003A
Email Address	YAP.JEFFERY@HOTMAIL.COM
Mobile Phone No	(Phone) +65-90070999
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10450812R02

DRIVER

Name of Driver	JEFFERY YAP CHOON MING
NRIC No	S7178003A
Date Of Birth	13/11/1971
Occupation	Indoor

Date of accident: 20/1/2023

Time: 5:00pm


Location: Woodlands Crossing towards Woodlands CIQ

Vehicle A: SMF 3859J

Vehicle B: SMC 3138Y

Vehicle C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/1/2023 at 5:00pm I was driving my vehicle (A) SMF3859J along Woodlands crossing towards woodlands CIQ. The traffic was heavy. In front of my vehicle stop and my vehicle also stop. Suddenly, the vehicle (B) SMC3138Y cannot stop in time and hit onto my vehicle rear portion.

☐ Claim OD/TP at Ah Lim Motor

☒ Claim OD/TP at other workshop

☐ Reporting Only

Yee Auto Pte Ltd

yeeautopteltd@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

27/1/2023
2:05pm

GIAPMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

27/1/2023
2:05pm

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

AH LIM MOTOR COMPANY