

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0092/2023/EQ
DATE : 27-Jan-23
WIP : 59929

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S GLOBAL ESPLANADE PTE LTD
ADDRESS : 19 KEPPEL ROAD
#03-07
SINGAPORE 089058
TELEPHONE : HP +65 97546006
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220094400
VEHICLE NO : **SGH 168 A**
MODEL CODE : AUDI E-TRON 50 QUATTRO GE
MODEL YEAR : 29/8/2022
ENGINE NO : EAS 167586
CHASSIS NO : WAUZZZGE3NB041928
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Dec-22
PLACE OF ACCIDENT : RED-LIGHT JUNCTION OF EAST COAST ROAD AND FRANKEL AVENUE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGH 168 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO CARRY OUT DE-ENERGISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$ 480.00	✓ ✓
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 900.00	✗
4	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,350.00	600 ✓
5	TO RESPRAY FRONT BUMPER	\$ 1,200.00	600 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 4,602.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 168 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	1	\$ 3,066.00	x
2	FRONT BUMPER TRIM - LH / RH <i>new</i>	2	\$ 138.00	+
3	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 689.00	x
4	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new d. Not at</i>	1	\$ 263.00	? 210
5	FRONT BUMPER FOAM PART - LH <i>new</i>	1	\$ 36.00	+
6	FRONT BUMPER GRILLE BRACKET COVER - LH / RH <i>new</i>	2	\$ 82.00	? x
7	FRONT BUMPER GRILLE INSULATOR - UPPER <i>new</i>	1	\$ 159.00	? x
8	FRONT BUMPER GRILLE INSULATOR - LOWER <i>new</i>	1	\$ 133.00	? 106
9	FRONT BUMPER PLASTIC FOAM STRIP <i>int</i>	1	\$ 143.00	✓ 114
10	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	1	\$ 300.00	✓ 239.60
11	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 181.00	? 144.40
12	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$ 248.00	x
13	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 214.00	x
14	FRONT BUMPER IMPACT PROTECTION <i>new</i>	1	\$ 953.00	x
15	FRONT BUMPER SPOILER - LH / RH <i>new</i>	2	\$ 234.00	x
16	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 128.00	x
17	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 100.00	x
18	RADIATOR AIR GUIDE - LH / RH	2	\$ 282.00	x
19	RADIATOR GRILLE <i>new</i>	1	\$ 2,466.00	✓ 172.80
20	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 149.00	x
SUB TOTAL SPARE PARTS		:	\$ 9,964.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 168 A
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	RADIATOR GRILLE BRACKET <i>Not Rec</i>	1	\$ 111.00	7 X
22	RADIATOR GRILLE SECURING PLATE <i>Not Rec</i>	1	\$ 99.00	7 X
23	RADIATOR GRILLE COVER <i>Not Rec</i>	1	\$ 74.00	7 X
24	RADIATOR GRILLE CLOSING ELEMENT <i>Not Rec</i>	1	\$ 262.00	7 X
25	RADIATOR GRILLE COVER - LH / RH <i>Not Rec</i>	2	\$ 130.00	7 X
26	FRONT "360" CAMERA <i>Rec</i>	1	\$ 1,115.00	+
27	FRONT BUMPER REINFORCEMENT BEAM <i>Rec</i>	1	\$ 1,536.00	+
28	FRONT BUMPER CROSS MEMBER <i>Rec</i>	1	\$ 491.00	+
29	FRONT BUMPER GUIDE SECTION - LH / RH <i>Rec</i>	2	\$ 106.00	+
30	FRONT BUMPER SHUTTER AIR BRACKET <i>3 Rec</i>	1	\$ 509.00	+
31	FRONT BUMPER BRACKET - LH / RH <i>3 Rec</i>	2	\$ 184.00	+
32	FRONT BUMPER TOP COVER <i>3 Rec</i>	1	\$ 125.00	+
33	FRONT BUMPER COVER	1	\$ 126.00	+
34	FRONT PARKING AID SENSOR - INNER <i>3 Rec</i>	2	\$ 598.00	+
35	FRONT PARKING AID SENSOR - OUTER	2	\$ 598.00	+
36	HEADLIGHT - LH / RH <i>3 Rec</i>	2	\$ 18,354.00	+
37	LIFT CYLINDER - LH / RH <i>Not Rec</i>	2	\$ 548.00	+
38	LIFT CYLINDER HOSE	1	\$ 115.00	+
39	RADIATOR AIR GUIDE - LH / RH <i>Not Rec</i>	2	\$ 78.00	+
40	RADIATOR AIR GUIDE - UPPER / LOWER <i>Dmgd</i>	2	\$ 89.00	70.80
SUB TOTAL SPARE PARTS		:	\$ 25,248.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGH 168 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	RADIATOR AIR GUIDE - UPPER / LOWER REAR <i>new</i>	2	\$ 187.00	+
42	HEADLIGHT SEAL - LH / RH <i>3 new</i>	2	\$ 126.00	+
43	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 686.00	✓ 548
44	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	✓ 60
45	SUNDRIES ?		\$ 400.00	+
TOTAL SPARE PARTS		:	\$ 36,671.00	
TOTAL LABOUR CHARGES		:	\$ 4,602.00	
GRAND TOTAL		:	\$ 41,273.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Li*
SURVEYED DATE : *31/07/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT