

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 01 Feb 2023

Preliminary Advice

Vehicle No	: SGH168A	Accident Date	: 29/12/2022
Make	: AUDI E-TRON	Policy No.	: 7220094400
Assignment Date	: 01/02/2023	Excess	: S\$0.00
Date of Inspection	: 31/1/2023	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,273.00
Revised Amount	:S\$	6,960.00
Check Items (Estimated)	:S\$	1,894.00
Total	:S\$	8,854.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	290,000.00
COE / PARF Rebate	:S\$	136,998.00
Salvage Value	:S\$	
Margin for Repair	:S\$	153,002.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .