

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SFB 6883Y
OD/Lonpac

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department

Claim No: ES2300095
Estimate No: ES2300095/YISHUN
Date: 01 Feb 2023
Policy No: Z22VP05031963
Veh Reg No: SFB6883Y
Make/Model: MERCEDES MERC
BENZ E200 EXCLUSIVE
(R18 LED)
Chassis No: WDD2130422A027556
Engine No: 27492030690197
Reg. Date: 15/09/2016

WS Ref: OD/LONPAC
Claim Type: Own Damage
Accident Date: 21/01/2023

Estimate Repair Cost to Vehicle No : SFB6883Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT LH DOOR GLASS OUTER MOULDING	78.00	1 PC	78.00	
2 TAILLAMPS	405.00	2 PCS	810.00	
3 REAR BOOT LOGO	35.00	1 PC	35.00	
4 REAR BOOT EMBLEM (E200)	90.00	1 PC	90.00	
5 BONNET LOGO	56.00	1 PC	56.00	
			1,069.00	
	Add 15%		160.35	1,229.35
Labour				
6 REMOVE & REFIX ALL NECESSARY PARTS TO ENABLE TO PUTTY & RESPRAY PAINTING,KNOCK & REPAIR REAR RH FENDER AND REALIGN THE SAME	600.00	1 LA	600.00	
7 PUTTY & RESPRAY ON BONNET,FRT BOTH FENDERS,FRT BUMPER,FRT & REAR LH DOORS,FRT & REAR RH DOORS,REAR BUMPER,REAR BOTH FENDERS,BONNET,RH SIDE MIRROR,FUEL TANK DOOR PANEL, TOP ROOF	2,800.00	1 LA	2,800.00	
				3,400.00
			Total	S\$ 4,629.35
			Add GST @ 8%	370.35
			Total Amount payable	<u>S\$ 4,999.70</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE