

Vehicle Damage Assessment Report for [SFE6655Z]

Estimate Created: 10/03/2023 16:17 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 10/03/2023 16:36 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SFE6655Z	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$4,250.00 WITH 5 WORKING
DAYS.

Insurlogic 4 (10/03/2023 16:36)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
tailgate lid		1	1218.45	-25.00 %	913.84
tailgate Prius emblem		1	63.90	-25.00 %	47.93
tailgate Hybrid emblem		1	61.10	-25.00 %	45.83
tailgate lid inner lock		1	374.45	-25.00 %	280.84
tailgate lid inner garnish		1	781.90	-25.00 %	586.43
o/s rear taillamp		1	681.90	-25.00 %	511.43
o/s taillamp lower bracket		1	132.50	-25.00 %	99.38
rear bumper		1	823.00	-25.00 %	617.25
o/s rear bumper side retainer		1	132.45	-25.00 %	99.34
rear end panel		1	687.30	-25.00 %	515.48

Parts Subtotal 3,717.75

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
rear parking sensor		1.0	200.00	0.00 %	200.00
rear windscreen glass sealant		1.0	40.00	0.00 %	40.00

Materials Subtotal 240.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
remove and refix rear windscreen glass	RnR	120.00	0.00 %	120.00
Anti rust	RnR	60.00	0.00 %	60.00
Wiring	RnR	20.00	0.00 %	20.00
Panel Beating	RnR	600.00	0.00 %	600.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 800.00

Paint Labor Subtotal 600.00

Labor Subtotal 1,400.00

Summary

Repair Cost	5,357.75
Discount(20 %)	(1,071.54)
	4,286.21
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,286.21