



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Ref: CS/INC23001026/Wqp3 Date: 01/02/2023 Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 7164K	Veh. Inspected	SMP 5607D	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1207770-002	Excess (\$)	0.00	
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	01/02/2023	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/01/2023	Inspection Date	01/02/2023	
Survey held at	BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 451875			
Repairer	SHIFTER AUTO GARAGE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				