

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0124/2023/EQ
DATE : 2-Feb-23
WIP : 61299

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/2/2023
YOUR INSURED VEH NO : SGM 8833 J

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR VISHAL SINHA
ADDRESS : 48 JALAN TUA KONG
SINGAPORE 457248

TELEPHONE : HP +65 87171500
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/01150388
VEHICLE NO : **SMH 1289 G**
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU
MODEL YEAR : 11/1/2019
ENGINE NO : DAX047584
CHASSIS NO : WAUZZZF2J2246646
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Jan-23
PLACE OF ACCIDENT : INTERSECTION OF MARINA BLVD AND SHEAVES AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 1289 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	
2	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$	1,800.00	
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS B-PILLAR, LHS SILL PANEL AND LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,500.00	
4	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, HINGES, 2 DOOR COVERS, LHS B-PILLAR, LHS SILL PANEL, LHS REAR FENDER, DOOR ENTRANCES AND LHS REAR WHEEL ARCH TRIMS.	\$	6,000.00	
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 12,572.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1289 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH	1	\$ 4,645.00	
2	FRONT DOOR OUTER SEAL	1	\$ 242.00	
3	BONDING AGENT	1	\$ 51.00	
4	CLEANING SOLUTION	1	\$ 80.00	
5	APPLICATOR	1	\$ 9.00	
6	FRONT DOOR CATCH - LH	1	\$ 172.00	
7	FRONT DOOR COVER - LH	1	\$ 884.00	
8	REAR DOOR - LH	1	\$ 4,645.00	
9	REAR DOOR OUTER SEAL	1	\$ 242.00	
10	BONDING AGENT	1	\$ 51.00	
11	CLEANING SOLUTION	1	\$ 80.00	
12	APPLICATOR	1	\$ 9.00	
13	REAR DOOR SEALING STRIP	1	\$ 23.00	
14	REAR DOOR ATTACHMENT PARTS	1	\$ 235.00	
15	REAR DOOR CATCH - LH	1	\$ 172.00	
16	REAR DOOR OUTER SEAL - LH	1	\$ 261.00	
17	REAR DOOR INNER SEAL - LH	1	\$ 242.00	
18	REAR SILL PANEL SEAL - LH	1	\$ 298.00	
19	REAR DOOR HINGE HALF UPPER PART - LH UPPER	1	\$ 56.00	
20	REAR DOOR HINGE HALF LOWER PART - LH UPPER	1	\$ 56.00	
SUB TOTAL SPARE PARTS		:	\$ 12,453.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1289 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HINGE HALF UPPER PART - LH LOWER	1	\$ 56.00	
22	REAR DOOR HINGE HALF LOWER PART - LH LOWER	1	\$ 56.00	
23	REAR DOOR COVER - LH	1	\$ 771.00	
24	REAR WINDOW REGULATOR - LH	1	\$ 354.00	
25	REAR WINDOW REGULATOR MOTOR - LH	1	\$ 430.00	
26	REAR WHEEL COVER - LH	1	\$ 653.00	
27	REAR ALUMINIUM RIM - LH	1	\$ 2,153.00	
28	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	
29	AIRBAG / CHILD'S SEAT STICKER WITH PICTOGRAM	1	\$ 28.00	
30	REAR WHEEL HOUSING LINER - LH	1	\$ 326.00	
31	STONE CHIP	S/N	\$ 180.00	
32	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 17,864.00	
TOTAL LABOUR CHARGES		:	\$ 12,572.00	
GRAND TOTAL		:	\$ 30,436.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT