



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

NAME: Lonpac Insurance Bhd
COMPANY NAME: Lonpac Insurance Bhd
STREET ADDRESS: 300 Beach Road, #17-04/06 The Concourse
POSTAL CODE: Singapore 199555
PHONE: 6250 7388

DATE: 31/1/2023

REF: SLC3911T
VEHICLE NO.: SLC3911T
MAKE: HONDA
MODEL: VEZEL
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	<u>LABOUR</u>						
1	TO REMOVE & REFIT FRONT LIGHTINGS (HEADLAMP & FOGLAMP) TO ASSIST FOR REPAIR	1		\$80.00	\$ 80.00		\$ 80.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS AND REALIGN	1		\$400.00	\$ 400.00		\$ 400.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	1		\$400.00	\$ 400.00		\$ 400.00
	<u>PARTS</u>						
1	FRONT NO PLATE WITH CASING	1		\$45.00	\$ 45.00		\$ 45.00
2	FRONT BUMPER	1		\$807.00	\$ 807.00		\$ 807.00
3	FRONT BUMPER CLIPS	10		\$5.50	\$ 55.00		\$ 55.00
4	FRONT BUMPER SIDE RETAINER LH & RH	2		\$28.00	\$ 56.00		\$ 56.00
5	FRONT BUMPER UPPER GRILLE	1		\$301.00	\$ 301.00		\$ 301.00
6	FRONT BUMPER UPPER GRILLE GARNISH	1		\$251.00	\$ 251.00		\$ 251.00
7	FRONT BUMPER UPPER GRILLE GARNISH LOGO	1		\$28.00	\$ 28.00		\$ 28.00
8	FRONT BUMPER LOWER GRILLE	1		\$79.00	\$ 79.00		\$ 79.00
9	FRONT BUMPER REINFORCEMENT	1		\$298.00	\$ 298.00		\$ 298.00
10	FRONT BUMPER LOWER SPOILER	1		\$221.00	\$ 221.00		\$ 221.00
SUBTOTAL					\$ 3,021.00	SUBTOTAL	\$ 3,021.00
GST 8%					\$ 241.68	GST 8%	\$ 241.68
TOTAL					\$ 3,262.68	TOTAL	\$ 3,262.68

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)