

(08/11/13) wof

ASS. REC. BY: ARC

REF: C66/CT123001040/Rpa3

1240

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMU 44681at Workshop m/s ARCof AG, TONG KUAN ROBOT #02-146

Insured:

CTI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

95K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lam Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMU 44681

Yr Regn:

2020 / 1240

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai AP NANTB 1.6 GLS S cc 1591

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

45621

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH0841CMLU099898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/01/23

D.O.I.

01/02/23

Survey held at

ARC

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

FRT 2 O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 58K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 62504489 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2301-068-TG

DATE : 31-Jan-2023

VEHICLE REG. NO. : SMU4468T

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A)

REG : 14 Aug 20

TO China Taiping

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper <i>repair</i>	1		\$ -
2	Front Bumper Retainer RH LH <i>X</i>	2		\$ -
3	Front Bumper Lower Moulding RH - 86571P <i>X</i>	1		\$ -
4	Front License Plate Garnish <i>de</i>	1		\$ -
5	Front Bumper Under Lip Assy - 86590E <i>X</i>	1		\$ -
6	Front Reinforcement <i>X</i>	1		\$ -
7	Front Stiffener 86571L <i>X</i>	1		\$ -
8	Front Sponge <i>3?</i>	1		\$ -
9	Front Grille (with Emblem) <i>?</i>	1		\$ -
10	Front Grille Bracket RH LH 86553B <i>X</i>	2		\$ -
11	Support Panel Top Cover 86360M <i>X</i>	1		\$ -
12	Headlamp RH LH <i>X</i>	2		\$ -
13	Headlamp Bracket RH LH <i>X</i>	2		\$ -
14	Support Panel <i>X</i>	1		\$ -
15	Rear Bumper <i>turn</i>	1		\$ -
16	Rear Bumper Lower <i>cm</i>	1		\$ -
17	Rear Bumper Retainer RH LH <i>X</i> <i>ipc</i>	<i>2</i>		\$ -
18	Rear license Plate Garnish <i>X</i>	1		\$ -
19	Rear Reflector RH LH 92405F <i>mis</i>	2		\$ -
20	Rear Bumper Cover RH 86690A <i>mis</i>	1		\$ -
21	Rear Reinforcement 86631D <i>cm</i>	1		\$ -
22	Rear Reinforcement Stay RH LH 86641A <i>X</i>	2		\$ -
23	Rear key Antenna 95420H <i>X</i>	1		\$ -
24	Rear Bumper Guard RH 86352W <i>?</i>	1		\$ -
25	End Panel <i>bt</i>	1		\$ -
26	End Panel Garnish <i>de</i>	1		\$ -
27	Spare Tyre Sink <i>X</i>	1		\$ -
28	Bootlid <i>bt</i>	1		\$ -
29	Bootlid Hinge RH LH <i>X</i>	2		\$ -
30	Bootlid Emblem <i>na</i>	1		\$ -
31	Bootlid Emblem S <i>m</i>	1		\$ -
32	Bootlid Emblem Avante <i>m</i>	1		\$ -

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 62504489 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2301-068-TG

DATE : 31-Jan-2023

VEHICLE REG. NO. : SMU4468T

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A)

REG : 14 Aug 20

TO China Taiping

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
33	Bootlid Inner Trim <i>de</i>	1		\$ -
34	Bootlid Hinge Torsion RH LH <i>X</i>	2		\$ -
35	Bootlid Locky Assy 81260B <i>X</i>	1		\$ -
36	Bootlid Latch Assy 81230 <i>X</i>	1		\$ -
37	Bootlid Striker 81210B <i>X</i>	1		\$ -
38	Boot Weatherseal <i>nu</i>	1		\$ -
39	Bootlid Lamp RH <i>?</i>	1		\$ -
40	Rear Fender Complete RH 70200A <i>bu</i>	1		\$ -
41	Tail Lamp Panel RH 71585 <i>bt</i>	1		\$ -
42	Tail Lamp RH <i>cm</i>	1		\$ -
43	Tail Lamp Clip <i>nu</i>	1		\$ -
44	Rear Fendershield RH Front <i>de</i>	1		\$ -
45	Rear Fendershield RH Back <i>mis</i>	1		\$ -
46	Rear Fendershield RH Mudguard <i>mis</i>	1		\$ -
47	Exhaust Muffler <i>rgau</i>	1		\$ -
48	Exhaust Mounting Bush <i>X</i>	1		\$ -
Total Spare Parts				\$ -
SPECIAL NETT				
49	Front License Plate with Casing <i>bt</i>	1	\$ 40.00	\$ 40.00 <i>35</i>
50	Rear License Plate with Casing <i>scr</i>	1	\$ 40.00	\$ 40.00 <i>35</i>
51	Front Bumper Clips <i>nu X</i>	10	\$ 3.00	\$ 30.00 <i>X</i>
52	Rear Bumper Clips <i>nu</i>	10	\$ 3.00	\$ 30.00 <i>/</i>
53	Rear Fendershield Clips <i>nu</i>	10	\$ 3.00	\$ 30.00 <i>/</i>
54	Bootlid Inner Trim Clips <i>nu</i>	10	\$ 3.00	\$ 30.00 <i>/</i>
55	New Parts Edge Sealant (Bootlid) <i>nu</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
56	Reverse Sensors <i>nu</i>	1	\$ 280.00	\$ 280.00 <i>200</i>
Total Special Nett				\$ 540.00
LABOUR				
57	Remove, Refit, Replace and Repair Affected Area	1	\$ 2,200.00	\$ 2,200.00 <i>1200</i>
58	Spray painting (Front Bumper, Rear Bumper, Rear Fender LH, Bootlid, End Panel, Tyre Sink)	1	\$ 1,500.00	\$ 1,500.00 <i>1000</i>
59	Remove & Replace Reverse Sensor	1	\$ 80.00	\$ 80.00 <i>40</i>
60	Wheel Alignment	1	\$ 70.00	\$ 70.00 <i>X</i>

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 62504489 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2301-068-TG

DATE : 31-Jan-2023

VEHICLE REG. NO. : SMU4468T

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A)

REG : 14 Aug 20

TO China Taiping

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT COST	TOTAL COST
61	Anti Rust Proofing	3	\$ 40.00	\$ 120.00
62	Run OBD Diagnosis and Clear Faults	1	\$ 150.00	\$ 150.00
63	Check/Rectify Wiring	1	\$ 20.00	\$ 20.00
Estimate prepared by: KenGuan				Total Labour \$ 4,140.00
The above is an estimate based on our inspection and does not cover any additional parts/labour which may be required after work has been started. Worn or damaged parts are discovered which may not be evident on first inspection. Because of this,				Amount Before Excess \$ 4,680.00
				Add GST @ 8% 374.40
				Total Amount Payable \$ 5,054.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ratna
Hp 90010068
9 days
L/S
01/02/23 @ 1450
Reg after repair

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	124D
Vehicle No.:	SMU4468T
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Feb 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A) S
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	G4FGLU111803
Chassis No.:	KMHD841CMLU099898
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$15,036.00
Original Registration Date:	14 Aug 2020
First Registration Date:	14 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$15,036.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2030
PARF Rebate Amount:	\$11,277.00
COE Expiry Date:	13 Aug 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,000.00
COE Rebate Amount:	\$24,847.00
Total Rebate Amount:	\$36,124.00

The information contained herein is correct as at 02 Feb 2023

Hyundai Avante 1.6A GLS S

Overview

Financial

Accessories

Similar

Research

Photos

Map

Autotruster Traders Pte Ltd
where cars are get currency



Price

\$95,800

Depreciation ⓘ

\$11,670 /yr

[View models with similar depreciation](#)

Reg Date

25-Aug-2020

(7yrs 6mths 22days COE left)

Mileage

32,118 km (13.2k /yr)

Manufactured ⓘ

2020

Road Tax ⓘ

\$738 /yr

Transmission

Auto

Dereg Value ⓘ

\$38,313 as of today (change)

OMV ⓘ

\$15,080

COE ⓘ

\$35,710

ARF ⓘ

\$15,080

Engine Cap

1,591 cc

Power

93.8 kW (125 bhp)

Cumulative Mileage ⓘ 1.345 kn

No. of Owners

1