

**FINAL BILL**

Name: AIG Asia Pacific Insurance Pte Ltd
 Address: Motor Claims Department
 78 Shenton Way #07-16
 AIG Building Singapore 079120

Ref Date: 12/02/2023
 Ref No: GBJ399Z230128
 Vehicle No: GBJ399Z
 Model / Make: Nissan
 Capacity: 1461 cc NV200 1.5 MT

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper	\$ 632.70	1	\$ 632.70		\$ -
2		Bumper Clips 1set	\$ 40.00	1	\$ 40.00	SN	\$ -
3		Bumper Sponge	\$ 182.50	1	\$ 182.50		\$ -
4		End Panel Outer	\$ 411.80	1	\$ 411.80		\$ -
5		End Panel Inner	\$ 455.20	1	\$ 455.20		\$ -
6		End Panel Top Garnish	\$ 108.60	1	\$ 108.60		\$ -
7		Bumper Reverse Sensor	\$ 220.00	1	\$ 220.00	SN	\$ -
8	Rear Rh	Bumper Reflector Rh	\$ 45.00	1	\$ 45.00		\$ -
9		Tailgate	\$ 1,102.30	1	\$ 1,102.30		\$ -
10		Tailgate Lower Lock	\$ 115.00	1	\$ 115.00		\$ -
11		Tailgate Lower Hinge	\$ 102.80	1	\$ 102.80		\$ -
12		Tailgate Inner Trim	\$ 166.20	1	\$ 166.20		\$ -
13		Tail Lamp	\$ 319.70	1	\$ 319.70	N	\$ -
14		Tailgate "6 PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	\$ -
15		Windscreen Glass Sealant	\$ 80.00	1	\$ 80.00	SN	\$ -
16	Rear Lh	Tailgate	\$ 1,545.40	1	\$ 1,545.40		\$ -
17		Tailgate Windscreen Glass	\$ 580.00	1	\$ 580.00		\$ -
18		Windscreen Glass Sealant	\$ 80.00	1	\$ 80.00	SN	\$ -
19		Tailgate "NV 200" Emblem	\$ 163.50	1	\$ 163.50	N	\$ -
20		Tailgate "NISSAN" Logo Motif	\$ 155.90	1	\$ 155.90	N	\$ -
21		Tailgate "70 KM/H" Sticker	\$ 15.00	1	\$ 15.00	SN	\$ -
22		Remove & reinstall RH & LH Tailgate Glass to facilitate repairs			\$ 240.00		\$ -
23		To check all wiring & electrical component for proper function			\$ 60.00		\$ -
24		Remove and refix rear Rh & Lh tailgate components & mechanism			\$ 120.00		\$ -
25		Remove and refix rear bumper reverse sensor			\$ 80.00		\$ -
26		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 800.00		\$ -
27		To putty & spray painting & including touch up paint on accident affected areas			\$ 900.00		\$ -
28		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 100.00		\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 8,836.60

Total amount in Lumpsum Basis for repaired vehicle

\$ 4,300.00

SDL Four Thousand Three Hundred Only



