



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR23001056/Rcp3e2 Date: 17/07/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 647D	Veh. Inspected	SKD 4873U	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/01/23/2053	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	02/02/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA JAZZ 1.3L A	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JHMGE68509S239504	Colour	GREY	
Odometer	151676 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	FALKEN	6 mm	
L/H Front Tyre	185/55 R16	FALKEN	6 mm	
R/H Rear Tyre	185/55 R16	FALKEN	6 mm	
L/H Rear Tyre	185/55 R16	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/01/2023	Inspection Date	06/02/2023	
Survey held at	42 TOH GUAN ROAD EAST #01-79			
Repairer	WAH HONG MOTORS & CREDIT PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	