



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|--|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CS3/CTI23001059/Wnp3 Date: 02/02/2023 Code: CTI | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | SMY 4500L | Veh. Inspected | SLE 4042J | |
| Policy No. | DMPCSNW00066612201 | Coverage (\$) | 0.00 | |
| Claim No. | SNM23D200691/C02/LEEPG | Excess (\$) | 0.00 | |
| Assign From | CECILIA LEE | Assign Date | 01/02/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | c.c | | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | Colour | | | |
| Odometer | - | Steering | | |
| Brakes | Modification | | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 27/01/2023 | Inspection Date | 01/02/2023 | |
| Survey held at | PERFECT MOTOR 51 DEFU LANE 9 DEFU INDUSTRIAL ESTATE SINGAPORE 539291 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | |