

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 5599U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		795.00	530.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		616.00	446.00
			1,411.00	976.00
	GRAND TOTAL		1,411.00	976.00

RECOMMENDED COST OF REPAIRS (CONFIRMED) 976.00

Report Ref No. NS/INC23001083/Gvy3e2

XING GUO QIANG

Automotive Assessor

M.MATAI, AMSAE-A

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser