

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 02 Feb 2023)

Parts: 143
Labour: Repairer's

NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
(Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SMW6356J/02/02/2023 12:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC FRT BUMPER	0.00	0.00	*350.00 F	DIS
2	1		*1 PC FRT BUMPER REINFORCEMENT	0.00	0.00	*280.00 F	?
3	1		*1 PC FRT BUMPER SPONGE	0.00	0.00	*100.00 F	?
4	1		*6 PCS FRT BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F	NEC
5	1		*1 PC FRT BUMPER CENTRE LOWER GRILLE	0.00	0.00	*115.00 F	?
6	1		*1 PC FRT TOW COVER	0.00	0.00	*25.00 F	XNN
7	1		*1 PC FRT GRILLE	0.00	0.00	*320.00 F	CRA
8	1		*1 PC FRT GRILLE LOGO	0.00	0.00	*50.00 F	CUT
9	1		*4 PCS FRT GRILLE CLIPS @2/PC	0.00	0.00	*8.00 F	NEC
10	1		*1 PC FRT SUPPORT TOP GARNISH	0.00	0.00	*130.00 F	?
11	1		*1 PC BONNET	0.00	0.00	*480.00 F	BUC
12	1		*1 PC LH HEADLAMP	0.00	0.00	*520.00 F	?
13	1		*1 PC LH FOG LAMP GARNISH	0.00	0.00	*55.00 F	XNN

F=Franchise part.

Sub Total (\$\$)	2,445.00
+ Margin on L,N Items 10.00% (\$\$)	244.50
Total Parts (\$\$)	2,689.50

Cheng Hoe Motor Pte Ltd/SMW6356J/02/02/2023 12:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 PC FRT NUMBER PLATE	35.00
Sub Total (S\$)			35.00

CRA

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE & REFIX FRT BUMPER ASSY, FOG LAMPS, GRILLE, BONNET & ATTACHMENT, HEADLAMPS, TO KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME	New	600.00
2	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00
3	PUTTY & RESPRAY ON FRT SUPPORT PANEL, FRT BUMPER, FRT BONNET	New	700.00
Gross Labour Cost (S\$)			1,400.00

400

X

500

Cheng Hoe Motor Pte Ltd/SMW6356J/02/02/2023 12:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*X/s read ↓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- P/P

- Excess \$600/2

- 4 days to repair.

- Not Authorise.