



MIRAGE MOTORWERKZ PTE LTD

Main Branch

10 Kaki Bukit Road 2
#01-28 / 29 First East Centre
Singapore 417868
+65 6635 7111 +65 6635 7112

East Coast Branch

Shell Autoserv @ Siglap
40 Upper East Coast Road
Singapore 455212
+65 6977 7117

admin@miragemw.sg

www.miragemw.sg

www.facebook.com/TeamMirage

ESTIMATED REPAIR CHECKLIST

TP Allianz Hui Roy 10/2/2023

TO :	VEHICLE REGISTRATION NO.: SLK7492S
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: PEUGOET / 5008
CLAIM TYPE : OD PARTY CLAIM	CHASSIS NUMBER: VF30EBHGTGS198172
ACCIDENT DATE/TIME :	CONTACT PERSON :

PARTS	QTY	PER UNIT	PRICES
1 FRONT WING MIRROR ASSY <i>Distorted</i>	1	\$ 948.90	\$ 948.90
2 FRONT DOOR GLASS OUTER MOULDING <i>new</i>	1	\$ 149.80	\$ 149.80
Sub total		SUBTOTAL :	\$ 1,098.70
Less 10%		LESS 10% :	\$ 109.87
Total List		PARTS TOTAL :	\$ 988.83

948.90
854.01

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 200.00	100
2 SPRAY PAINTING	\$ 200.00	100
3 WIRING	\$ 50.00	30
LABOR TOTAL :	\$ 450.00	

230

total: 1084.01

1/5: 850

01 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: