

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	<u> </u>	Ref:	CS/SMR23001103/Rvy3m4		
		NDUSTRIAL PARK		ate:	31/03/2023	
			C	ode:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 5871P	Veh. Inspected		SMH 1208R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/01/23/2074	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		02/02/2023	
2. Vehicle Particulars & Condition						
	Make & Model	JAGUAR E-PACE 2.0P	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	SADFA2AX2K1Z45998	Colour		BLUE	
	Odometer	060072 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/60 R18	MICHELIN		6 mm	
	L/H Front Tyre	235/60 R18	MICHELIN		6 mm	
	R/H Rear Tyre	235/60 R18	MICHELIN		6 mm	
	L/H Rear Tyre	235/60 R18	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	30/01/2023	Inspection Date		06/02/2023	
	Survey held at	WEARNES AUTOMOTIVE PTE I	_TD			
		249 ALEXANDRA ROAD SINGAPORE 159935				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					