

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Zheng Hanyang

Date: 06 Feb 2023

**Preliminary Advice**

Vehicle No	: SJV9910E	Accident Date	: 31/01/2023
Make	: TOYOTA VIOS E	Policy No.	: DMPG22010587
Assignment Date	: 02/02/2023	Excess	: S\$500.00
Date of Inspection	: 3/2/2023	Est. Duration of Repair	: 7
Inspection At	: MOVA AUTOMOTIVE PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,697.00
Revised Amount	:S\$	7,900.80
Check Items (Estimated)	:S\$	2,411.20
Total	:S\$	10,312.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	57,000.00
COE / PARF Rebate	:S\$	23,342.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,658.00

**Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .