

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 Jan 2023 13:40	Clm Veh Model Changed		[] Merimen Administrator
2	30 Jan 2023 13:40	Clm Created	Reg No: SKE1912E. Policy No: 1800053988-04. Acct Date: 2023/01/28. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SA S:SP14231U0002	[I] Merimen Administrator
3	03 Feb 2023 14:37	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Rajeswari
4	03 Feb 2023 14:37	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Rajeswari
5	03 Feb 2023 14:37	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Rajeswari
6	03 Feb 2023 14:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/02/14	[A] Rajeswari
7	03 Feb 2023 14:37	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Rajeswari
8	03 Feb 2023 14:37	Clm Registration Modified	Rep:1137->200611.	[A] Rajeswari
9	03 Feb 2023 14:37	Clm Veh Model Changed	(203400) AUDI S5 SPORTBACK 3.0 (A).	[A] Rajeswari
10	03 Feb 2023 14:38	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Rajeswari
11	03 Feb 2023 15:11	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	03 Feb 2023 15:11	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	03 Feb 2023 15:11	Clm Dtl Modified	JPJ Reg. Date: -> 2018/05/15.	[A] Elaine Kuan Hwa Meen
14	03 Feb 2023 15:11	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	03 Feb 2023 15:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2023/02/14	[A] SHIAU CHAN
16	03 Feb 2023 15:38	Adj Mandate Request	Cur.Req:18456.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUT HORISE REPAIR.	[A] SHIAU CHAN
17	06 Feb 2023 12:03	Clm Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 3000.00. 2F Remarks: -> Not Applicable. GST: -> 8.0 0.	[I] Azlan, Syazairdina
18	06 Feb 2023 16:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/02/14. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
19	06 Feb 2023 16:29	Adj Mandate Set	Approved:17684.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From

Date To

Audit Type

None

Go

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2909691	03 Feb 2023 15:11:19	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKE1912E		11.00

